



PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE
 JTC AVIATION 2 BUILDING #09-07
 SELETAR AEROSPACE PARK
 65-6817-3370

797523
 SINGAPORE
 www.precisionaviationgroup.com
 GST: 201737172D

EXCHANGE QUOTE



Print Date : May-23-2022 11:45 PM

Printed By:Ratan Pandey Print No. : 1

For : Account No. [GALAXYMY]

No. 5604353

Pg:1/2

GALAXY AEROSPACE (M) SDN BHD
 Attn: AQILAH BINTI MOHD HANAFI
 SUITE 11-14, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 SULTAN ABDUL AZIZ SHAH AIRPORT
 SUBANG 47200
 MALAYSIA
 Tel. : +60377347226

Our Ref : Q5604353
Terms : PREPAID
Our Contact : Ratan Pandey
Valid Until : Jun-22-2022
Incoterms : FCA - FREE CARRIER (ORIGIN)
Quote Date : May-23-2022

In response to your request, we are pleased to quote you the following:

Line	P/N & Description	Cn	Qty Bid	Delivery	Unit Price	Amount
1	501-1860-0403 ESIS INDICATOR MFG: (L3) L-3 AVIATION PRODUCTS INC. Note: ** Exchange Charge- Core Return Required **	RP	1 EA	Stock	\$ 14,950.00 EA	\$ 14,950.00
2	501-1860-0403 ESIS INDICATOR MFG: (L3) L-3 AVIATION PRODUCTS INC. Note: ** Core Charge **	AR	1 EA	Stock		
3	81-101-5 FUEL QUANTITY INDICATOR ALT#: 117-384019-3 MFG: (RAGEN) RAGEN DATA SYSTEMS, INC. Note: ** Exchange Charge- Core Return Required **	OH	1 EA	Stock	\$ 1,495.00 EA	\$ 1,495.00
4	81-101-5 FUEL QUANTITY INDICATOR ALT#: 117-384019-3 MFG: (RAGEN) RAGEN DATA SYSTEMS, INC. Note: ** Core Charge [\$ 4,000.00]** Certification Type: FAA 8130 Exchange Policy	AR	1 EA	Stock		

Exchange prices are based on the customer returning a repairable core of the same part number. PAG reserves the option to reject any returned unit that has been damaged from abnormal causes, such as fire, crash, submersion,

Continued on next page...



PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE
 JTC AVIATION 2 BUILDING #09-07
 SELETAR AEROSPACE PARK
 65-6817-3370

797523
 SINGAPORE
 www.precisionaviationgroup.com
 GST: 201737172D

EXCHANGE QUOTE



Print Date : May-23-2022 11:45 PM Printed By:Ratan Pandey Print No. : 1

Our Ref : Q5604353 Quotation No. 5604353 Page:2/2

Line	P/N & Description	Cn	Qty Bid	Delivery	Unit Price	Amount
	<p>cannibalization, unauthorized repair or excessive wear. Units found to be economically non-repairable will be returned. Cost of any repair above normal charges which is found, either at the time of the exchange or later during overhaul, will be billed in addition to the exchange or later during overhaul. If an acceptable core is not received within 30 days of date of invoice, the applicable core charge will be due.</p> <p>All units quoted are subject to prior sale</p> <p>Freight: The shipping of all core returns and repairs to PAG is the sole responsibility of the customer. Any costs incurred by PAG including freight, Dangerous goods, customs clearance or delivery fees will be recharged to the customer.</p>					

					Sub Total:	\$ 16,445.00
					Total:	[USD] \$ 16,445.00

Ratan Pandey,