

## PRECISION HELIPARTS SINGAPORE PTE LTD

**Quote Date** 

690 WEST CAMP ROAD SINGAPORE JTC AVIATION 2 BUILDING #09-07 SELETAR AEROSPACE PARK 65-6817-3370

**SINGAPORE** www.precisionaviationgroup.com GST: 201737172D

## **EXCHANGE QUOTE**



Print Date : Jun-20-2022 10:11 PM

## For : Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD Attn: AQILAH BINTI MOHD HANAFI SUITE 11-14, HELICOPTER CENTRE, MALAYSIA BUTE AND ONLY ARROSPACE CENTRE

SULTAN ABDUL AZIZ SHAH AIRPORT SUBANG 47200 MALAYSIA

Tel.: +60377347226

In response to your request, we are pleased to quote you the following:

	Fillited by.natan Fandey	FIIIILINO
No. 560	4566	Pg:1/1
Our Ref Terms Our Contact eMail Valid Until Incoterms	: Q5604566 : PREPAID WIRE TRANSFR : Ratan Pandey : rpandey@heliparts.com : Jul-20-2022 : FCA - FREE CARRIER (ORIG	SIN)

: Jun-20-2022

Line	P/N & Description	Cn	Qty Bid	Delivery	Unit Price	Amount
1	822-1753-351 ADAPTIVE FLIGHT DISPLAY ALT#:AFD-3010E MFG: (C2737*8) ROCKWELL COLLINS - C	RP EDAR RAPI	1 EA	5 Days	\$ 35,750.00 EA	\$ 35,750.00
2	Note: ** Exchange Charge- Core Return Rec 822-1753-351 ADAPTIVE FLIGHT DISPLAY ALT#: AFD-3010E MFG: (C2737*8) ROCKWELL COLLINS - C	AR	1 EA	Stock		
	Note: ** Core Charge ** Certification Type: FAA 8130					
	Exchange Policy					
	Exchange prices are based on the customer the option to reject any returned unit that has cannibalization, unauthorized repair or exces Cost of any repair above normal charges wh will be billed in addition to the exchange or la of date of invoice, the applicable core charge	ich is tound, ater during o	either at the time of verhaul. If an accep	the exchange	or later during overhaul	
	All units quoted are subject to prior sale					
	Freight: The shipping of all core returns and Any costs incurred by PAG including freight, will be recharged to the customer.	repairs to Pa Dangerous	AG is the sole respo goods, customs clea	nsibility of the or arance or delive	customer. ry fees	
				`	Sub Total:	\$ 35,750.00
					Total: [USD]	\$ 35,750.00