

KESUMA TECHNOLOGY SDN.BHD

D-7-02, Capital 4, Oasis Square, No. 2, Jalan PJU 1A/7A, Ara Damansara, 47301 Petaling Jaya,

Selangor Darul Ehsan, MALAYSIA. Tel: +603-7832 2998/7398 Fax: +603-7832 4998

: GALAXY AEROSPACE (M) SDN BHD From : Kasim Hj Ismail

Suite 11-14, Helicopter Centre,

Malaysia International Aerospace Centre,

Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia

Phone: +603 7734 7226 : 04/07/2022 Date : +603 7734 7526 : USD Currency

Attn : Nor Izzati Azmi Reference : GALAXY/R/0024/2022

: QUOTATION FOR REPAIR Re

Please find our quotation with regards to your Purchase Order No: PO-22-4999

No.	Part No	Description	Serial No	Qty	Total Cost	Delivery (Status)
1	709-0103-01-109	MAIN ROTOR BLADE ASSY	J44994	1	51,052.00	30 days after your PO
	Breakdown					
	Detailed Inspection					
	1) Erosion Shield Replacement (Erosion Shield eroded through)					
	2) Tip Cap Replacement (Comply with SB109EP-148)					
	3) Rebond Data Tag (Tag debonded)					
	4) Root Bushing Replacement (Qty 2; Bushings out of tolerance) Skin Repair					

6) Complete Refinish and Statis Balance

Total Cost 51,052.00

Estimated / Price of New

Note:

1) Offer Validity : 30 days from the date of quotation 2) Terms of Payment : To be made in full before delivery

3) Cancellation : There will be 30% surcharge (imposed by AgustaWestland) for any cancellation

4) Delivery : Subject to prior sale

5) NDT & X-Ray Inspection (Skin damage)

: NEW/REPAIRED/OVERHAULED with Leonardo's Certificate of Conformance / EASA certificate 5) Condition 6) Confirmation : Confirmation of availability of goods will be given within 5 working days upon receipt of the official Purchase Order (PO) and customer's must respond to Kesuma Technology within 2

working days for confirmation of purchase

Warranty period shall be as follows:

1) New Condition : 12 months against manufacturer faults except for consumable items.

2) Repair Condition : 6 Months or 500 hrs against manufacturer faults.