

KESUMA TECHNOLOGY SDN.BHD

Co No: 76215

D-7-02, Capital 4, Oasis Square, No. 2, Jalan PJU 1A/7A, Ara Damansara, 47301 Petaling Jaya, Selangor Darul Ehsan, MALAYSIA.

: Kasim Hj Ismail

From

Tel: +603-7832 2998/7398 Fax: +603-7832 4998

To : GALAXY AEROSPACE (M) SDN BHD

Suite 11-14, Helicopter Centre,

Malaysia International Aerospace Centre,

Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia

Phone: +603 7734 7226 Date: 17/08/2022

Fax : +603 7734 7526 Currency : USD

Attn : Nor Izzati Azmi Reference : GALAXY/R/0027/2022

Re : QUOTATION FOR OVERHAUL & MODIFICATION

Please find our quotation with regards to your Purchase Order No: MMA-22-288

No.	Part No	Description	Serial No	Qty	Total Cost	Delivery (Status)
1	3G6730V00531	TAIL ROTOR ACTUATOR MK II	HSC221720	1	25,600.00	150 days after your PO
	Breakdown 1) Confirmed defect after Inspection/Functional test. 2) Item need to be Overhaul and Modification.					
			Total Cost	: =	25,600.00	

Estimated / Price of New

Note:

Offer Validity : 30 days from the date of quotation
 Terms of Payment : To be made in full before delivery

3) Cancellation : There will be 30% surcharge (imposed by AgustaWestland) for any cancellation

4) Delivery : Subject to prior sale

5) Condition : NEW/REPAIRED/OVERHAULED with Leonardo's Certificate of Conformance / EASA certificate
6) Confirmation : Confirmation of availability of goods will be given within 5 working days upon receipt of the

official Purchase Order (PO) and customer's must respond to Kesuma Technology within 2

working days for confirmation of purchase

Warranty period shall be as follows:

1) New Condition : 12 months against manufacturer faults except for consumable items.

2) Repair Condition : 6 Months or 500 hrs against manufacturer faults.

for KESUMA JECHNOLOGY SDN BHD