

**KESUMA TECHNOLOGY SDN.BHD**

(Co Reg: 782152-A)
D-7-02, Capital 4, Oasis Square,
No. 2, Jalan PJU 1A/7A, Ara Damansara,
47301 Petaling Jaya,
Selangor Darul Ehsan, MALAYSIA.
Tel : +603-7832 2998/7398
Fax : +603-7832 4998

To : **GALAXY AEROSPACE (M) SDN BHD**
Suite 11-14, Helicopter Centre,
Malaysia International Aerospace Centre,
Sultan Abdul Aziz Shah Airport,
47200 Subang, Selangor, Malaysia
Phone : +603 7734 7226
Fax : +603 7734 7526
Attn : **Nor Izzati Azmi**

From : Kasim Hj Ismail
Date : 12/10/2022
Currency : USD
Reference : GALAXY/R/0032/2022

Re : QUOTATION FOR OVERHAUL & MODIFICATION

Please find our quotation with regards to your Purchase Order No : MMA-22-287

No.	Part No	Description	Serial No	Qty	Total Cost	Delivery (Status)
1	3G6730V00731	TAIL ROTOR ACTUATOR MK II	HSC215962	1	28,964.00	180 days after your PO
<u>Breakdown</u> 1) Confirmed defect after Inspection/Functional test. 2) Item need to be Overhaul and Modification.						
Total Cost					: 28,964.00	

Estimated / Price of New :

Note :

- 1) Offer Validity : 30 days from the date of quotation
- 2) Terms of Payment : To be made in full before delivery
- 3) Cancellation : There will be 30% surcharge (imposed by AgustaWestland) for any cancellation
- 4) Delivery : Subject to prior sale
- 5) Condition : NEW/REPAIRED/OVERHAULED with Leonardo's Certificate of Conformance / EASA certificate
- 6) Confirmation : Confirmation of availability of goods will be given within 5 working days upon receipt of the official Purchase Order (PO) and customer's must respond to Kesuma Technology within 2 working days for confirmation of purchase

Warranty period shall be as follows :

- 1) New Condition : 12 months against manufacturer faults except for consumable items.
- 2) Repair Condition : 6 Months or 500 hrs against manufacturer faults.


For KESUMA TECHNOLOGY SDN BHD
