



PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE
 JTC AVIATION 2 BUILDING #09-07
 SELETAR AEROSPACE PARK
 65-6817-3370

797523
 SINGAPORE
 www.precisionaviationgroup.com
 GST: 201737172D

EXCHANGE QUOTE



Print Date : Apr-10-2023 10:08 PM

Printed By:Ratan Pandey Print No. : 1

For : Account No. [GALAXYMY]

No. 5606156

Pg:1/2

GALAXY AEROSPACE (M) SDN BHD
 Attn: NUR AFRINA AZHAR KHAN
 SUITE 11-14, HELICOPTER CENTRE,
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE
 SULTAN ABDUL AZIZ SHAH AIRPORT
 SUBANG 47200
 MALAYSIA
 Tel. : +603-7455 0555

Our Ref : Q5606156
Terms : PREPAID WIRE TRANSFR
Our Contact : Ratan Pandey
eMail : rpandey@heliparts.com
Valid Until : May-10-2023
Incoterms : FCA - FREE CARRIER (ORIGIN)
Quote Date : Apr-10-2023

In response to your request, we are pleased to quote you the following:

Line	P/N & Description	Cn	Qty Bid	Delivery	Unit Price	Amount
1	174250-92 OXYGEN MASK ALT#: 128-380067-29 MFG: (PURITAN) PURITAN-BENNETT/B/E Note: ** Exchange Charge- Core Return Required **	OH	2 EA	Stock	\$ 3,950.00 EA	\$ 7,900.00
2	174250-92 OXYGEN MASK ALT#: 128-380067-29 MFG: (PURITAN) PURITAN-BENNETT/B/E Note: ** Core Charge [\$ 10,000.00]**	AR	2 EA	Stock		
3	501-1228-04 POWER SUPPLY ALT#: PS-835D MFG: (B3115*8) L-3 COMMUNICATIONS AVIONICS SYST - FT LAUDERDALE Note: ** Exchange Charge- Core Return Required **	OH	1 EA	Stock	\$ 1,450.00 EA	\$ 1,450.00
4	501-1228-04 POWER SUPPLY ALT#: PS-835D MFG: (B3115*8) L-3 COMMUNICATIONS AVIONICS SYST - FT LAUDERDALE Note: ** Core Charge [\$ 3,000.00]** Certification Type: FAA 8130 Exchange Policy	AR	1 EA	Stock		

Continued on next page...



PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE
 JTC AVIATION 2 BUILDING #09-07
 SELETAR AEROSPACE PARK
 65-6817-3370

797523
 SINGAPORE
 www.precisionaviationgroup.com
 GST: 201737172D

EXCHANGE QUOTE



Print Date : Apr-10-2023 10:08 PM Printed By:Ratan Pandey Print No. : 1

Our Ref : Q5606156 Quotation No. 5606156 Page:2/2

Line	P/N & Description	Cn	Qty Bid	Delivery	Unit Price	Amount
	<p>Exchange prices are based on the customer returning a repairable core of the same part number. PAG reserves the option to reject any returned unit that has been damaged from abnormal causes, such as fire, crash, submersion, cannibalization, unauthorized repair or excessive wear. Units found to be economically non-repairable will be returned. Cost of any repair above normal charges which is found, either at the time of the exchange or later during overhaul, will be billed in addition to the exchange or later during overhaul. If an acceptable core is not received within 30 days of date of invoice, the applicable core charge will be due.</p> <p>All units quoted are subject to prior sale</p> <p>Freight: The shipping of all core returns and repairs to PAG is the sole responsibility of the customer. Any costs incurred by PAG including freight, Dangerous goods, customs clearance or delivery fees will be recharged to the customer.</p>					

					Sub Total:	\$ 9,350.00
					Total:	[USD] \$ 9,350.00

Ratan Pandey,