

Quote: GHC/SPB/MRO/404/2022-REV **Date:** June 27, 2022

GULF HELICOPTERS COMPANY

To: GALAXY AEROSPACE (M) SDN BHD Attn: Ashila Naja Mohd Zulkaple

MRO DEPARTMENT Al Areesh Street, Ras Abu Abboud

Office: +60377347226

P.O. Box: 811 Doha-Qatar

Email: ashila@galaxyaerospace.my

Tel: +974 44 333 888 www.gulfhelicopters.com

Dear Ashila Naja Mohd Zulkaple

Thank you for your valuable request to quote against your RFQ email reference URGENT/RFQ/GAM/PGUP/APMM/MAIN ROTOR DAMPER dated on 22 JUNE 2022.

We are pleased to quote for the same:

SECTION 1. DETAILS

#	Part Number	Description	QTY	CN	UoM	Lead Time	Unit Price (USD)	Total Price (USD)
OPTION A	3G6220V01353	MAIN ROTOR DAMPER	1	EXCHANGE RC	EA	30-60 DAYS	17,531.47	17,531.47
OPTION B	REQUESTING FOR PN: 3G6220V01353 QUOTING FOR: 3G6220V02051	MAIN ROTOR DAMPER	1	OVH OUTRIGHT	EA	20-30 DAYS	22,650.78	22,650.78
OPTION C	3G6220V01353	MAIN ROTOR DAMPER	1	REPAIR	EA	TAT: 2-3 WEEKS	9,400.00	9,400.00

SECTION 2. AOG

#	Part Number	Description	QTY	CN	UoM	Lead Time	Unit Price (USD)	Total Price (USD)
OPTION A	3G6220V01353	MAIN ROTOR DAMPER	1	EXCHANGE RC	EA	AOG : 7-10 DAYS	20,909.53	20,909.53
OPTION B	REQUESTING FOR PN: 3G6220V01353 QUOTING FOR: 3G6220V02051	MAIN ROTOR DAMPER	1	OVH OUTRIGHT	EA	AOG : 7-10 DAYS	28,604.44	28,604.44

TERMS & CONDITION:

- Payment Terms: Advance payment against Proforma Invoice;
- End user certificate: May require in advance or subject to the laws and conditions of the supplying country at the time of dispatch;
- Price quoted is based in quantity and line items quoted, changes in quantity or line items may result in price change;
- Subject prior to sale;
- Quote valid for 30 days;
- Duties and taxes extra as applicable;
- Delivery Ex works Doha;

OPTION A: EXCHANGE:

- •Core should be returned within 15 days of receipt of the unit against your order.
- •Core value will be determined only upon evaluation of log cards of the core
- Exchange quote based on return of economically repairable undamaged core removed from non-incident related aircraft. Core will be
 inspected in our vendor facility and any additional defects found during inspection and or the core unit is deemed to be BER, additional
 charges may apply.
 - Core should be returned with like part no. and it should be removed from the commercially operated / maintained aircraft within 30 days



OPTION C: REPAIR

- •TAT Calculation starts when the component is received from GHC repair facility, evaluated and considered eligible for repair, or from the acceptance of the Vendor's proposal by the client, whichever occurs last
- acceptance of the Vendor's proposal by the client, whichever occurs last

 •This Quotation is definitive, a revised repair quotation will be issued in case: during the repair activity it is necessary to perform additional works or to replace other components not estimated at this stage.
- ●Refusal fee is applicable should the client decline the final repair quote®
- Minimum order value : 250 USD;
- Cancellation of confirmed order is subject for fee of 25% of the total value of PO
- Freight charges will be billed extra
- Note: Upon placement of the order, the delivery can be expedited;
- Disclaimer: E & OE and force majeure;
- Please confirm the receipt.

Your sincerely, For Gulf Helicopters Co.

Ivee Opada

MRO/145 Commercial