

To:

**GALAXY AEROSPACE (M) SDN BHD**

79-1, 1st Floor, Jalan PJU 1A/41B, NZX Commercial Centre,  
Ara Damansara, 47301 Petaling Jaya, Selangor

Tel: +603-7887 0426

Faks: +603-7887 0526

Attn: En Nor Azman Huzir / En Faiz Fahmi Johari

From : Kasim Hj Ismail

Pages : 01

Date : 18-Feb-2020

Currency : USD

Aircraft Type/SN : A109E / AW139

Reference : GALAXY0204/02/2020

**RE: SPARES QUOTATION**

Below is the quotation for your RFQ: Email dated 11/02/2020

No	Part Number	Description	U.M	Qty	Unit Price	Total Price	Delivery Status
1	109-0310-98-101	LH Windshield	EA	1	4,954.87	4,954.87	120
2	109-0310-98-102	RH Windshield	EA	1	4,954.87	4,954.87	120
3	<b>999-1700-48-101G</b> (109-0360-82-102)	Seal (RH/L=2070 MM)	MTR	2.2	77.75	171.05	90
4	109-0360-49-211		EA	1		NOT SUPPLIABLE	
5	NAFTOSEAL MC-780		EA	2		NOT SUPPLIABLE	
6	SCOTCH-WELD EC-3549 B/A		EA	2		NOT SUPPLIABLE	
7	109-0360-85-103	Window, Dual Glasses LH	EA	1	3,357.71	3,357.71	270
8	109-0360-85-104	Window, Dual Glasses RH	EA	1	3,357.71	3,357.71	270
9	109-0324-33-171	Gasket	EA	2		-	TBA
10	109-0324-33-173	Filler	EA	2		-	TBA
11	109-0310-27-263	Panel Assy, Transparent LH	EA	1	4,410.15	4,410.15	90
12	109-0310-27-270	Panel Assy, Transparent RH	EA	1	4,410.15	4,410.15	90
13	MS20600AD4W	Rivet	EA	100		NOT SUPPLIABLE	
14	MS20600AD5W	Rivet	EA	100		NOT SUPPLIABLE	
15	<b>NAS9304B-4-02</b> (M7885/6-4-02)	Rivet	EA	100	2.42	242.00	90
16	RTV 732		EA	2		NOT SUPPLIABLE	
17	3G3210V00332	MLG Shock Absorber	EA	2	26,175.37	52,350.74	150
18	3G5610V00651	RH Windshield	EA	1	21,427.26	21,427.26	200
19	3G5610V00551	LH Windshield	EA	1	21,427.26	21,427.26	200
20	AN525-10R12	Screw	EA	38	0.59	88.50	90
				(MOQ:150)			
21	AN525-10R14	Screw	EA	54	0.46	69.00	90
				(MOQ:150)			
22	AN525-10R16	Screw	EA	7 (MOQ:80)	0.94	75.20	90
23	NAS1149C03136B		EA	99		PN NOT IDENTIFIED	
24	<b>3G5610A00633C1</b>	<b>RH Roof Window</b>	EA	1			
		<b>** Suppliable PN are either one:</b>					
24.1	3G5610A00633R	Upper RH Transparent Assy	EA	1	16,134.14	16,134.14	180
24.2	3G5610A00633A1N	Bronze Upper RH Transparent Assy Not Hol	EA	1	16,134.14	16,134.14	180
25	<b>3G5610A00733C1</b>	<b>LH Roof Window</b>	EA	1			
		<b>** Suppliable PN are either one:</b>					
25.1	3G5610A00733R	Upper LH Transparent Assy	EA	1	16,134.14	16,134.14	180
25.2	3G5610A00733A1N	Bronze Upper LH Transparent Assy Not Hol	EA	1	16,134.14	16,134.14	180
26	199-05-003	Gasket Tape (10 meter)	EA	1		NOT SUPPLIABLE	
27	3G6420V00455	Tail Rotor Damper	EA	1	6,975.90	6,975.90	120
28	N.A	Proseal 890	EA	1		NOT SUPPLIABLE	
29	N.A	Proseal 890B2	EA	1		NOT SUPPLIABLE	
30	42315-281	Cartridge	EA	1	3,749.35	3,749.35	90
31	42315-75-1	Cable Cutter Assy	EA	1	6,589.98	6,589.98	230
32	<b>AW002VF01WPN</b> (30-271-01WPN)	Connector Receptacle	EA	1	444.78	444.78	230
33	1768-107	Belt	EA	4	419.05	1,676.20	90
34	3G5610V00651	RH Windshield	EA	1	21,427.26	21,427.26	90
35	3G5610V00551	LH Windshield	EA	1	21,427.26	21,427.26	90

No	Part Number	Description	U.M	Qty	Unit Price	Total Price	Delivery Status
36	AN525-10R12	Screw	EA	38	0.59	88.50	90
				(MOQ:150)			
37	AN525-10R14	Screw	EA	54	0.46	69.00	90
				(MOQ:150)			
38	AN525-10R16	Screw	EA	7 (MOQ:80)	0.94	75.20	90
39	NAS1149C03136B	Washer	EA	99		PN NOT IDENTIFIED	
40	<b>3G5610A00633C1</b>	<b>RH Roof Window</b>	<b>EA</b>	<b>1</b>			
	<b>** Suppliable PN are either one:</b>						
40.1	3G5610A00633R	Upper RH Transparent Assy	EA	1	16,134.14	16,134.14	180
40.2	3G5610A00633A1N	Bronze Upper RH Transparent Assy Not Hol	EA	1	16,134.14	16,134.14	180
41	<b>3G5610A00733C1</b>	<b>LH Roof Window</b>	<b>EA</b>	<b>1</b>			
	<b>** Suppliable PN are either one:</b>						
41.1	3G5610A00733R	Upper LH Transparent Assy	EA	1	16,134.14	16,134.14	180
42.2	3G5610A00733A1N	Bronze Upper LH Transparent Assy Not Hol	EA	1	16,134.14	16,134.14	180
42	199-05-003		EA	1		NOT SUPPLIABLE	
43	N.A	Proseal 890	EA	1		NOT SUPPLIABLE	
44	N.A	Proseal 890B2	EA	1		NOT SUPPLIABLE	

**Grand Total : 312,893.02**

**Note:**

- 1) Offer validity : 30 days from the date of quotation
- 2) Terms of payment : To be made in full before delivery.
- 3) Cancellation : There will be 30% surcharge (imposed by AgustaWestland) for any cancellation
- 4) Delivery : Subject to prior sale
- 5) Condition : NEW/REPAIRED/OVERHAULED with Leonardo's Certification of Conformance / EASA certificate
- 6) Confirmation : Confirmation of availability of goods will be given within 5 working days upon receipt of the official Purchase Order (PO) and customer's must respond to Kesuma Technology within 2 working days for confirmation of purchase.

**Warranty period shall be as follows:**

- 1) New condition : 12 months against manufacturer faults except for consumable items.
- 2) Repair condition : 6 months or 500 hrs against manufacturer faults

*Handwritten signature*

for KESUMA TECHNOLOGY SDN BHD

