

## **KESUMA TECHNOLOGY SDN.BHD**

(Co No: 762152-X)

D-7-02, Capital 4, Oasis Square, No. 2, Jalan PJU 1A/7A, Ara Damansara, 47301 Petaling Jaya,

Selangor Darul Ehsan, MALAYSIA.

Tel: +603-7832 2998/7398 Fax: +603-7832 4998

(SST NO: B16-2207-32100006)

: Kasim Hj Ismail

## **QUOTATION**

To

**GALAXY AEROSPACE (M) SDN BHD** 

79-1, 1st Floor, Jalan PJU 1A/41B, NZX Commercial Centre,

Ara Damansara, 47301 Petaling Jaya, Selangor

Tel: +603-7887 0426 Faks: +603-7887 0526

Attn: Cik Nor Izzati Azmi / Cik Ashila Naja Mohd Zulkaple

From

Pages : 01 Date : 28-Nov-2022

Currency : **USD** AC Type/SN : **AW139** 

Reference : GALAXY369/11/2022

## RE: SPARE QUOTATION

Below is the quotation for your RFQ: Email on 23/11/2022

No	Part Number	Description	U.M	Qty	Unit Price	Total Price	Delivery Status
1	A864A1308E022H	SHIM, LAMINATED	EA	5	7.23	36.15	90
2	MS17826-4	NUT,SELF-	EA	30	4.00	120.00	90
		LOCKING, SLOTTED, HEXAGON					
3	3G6420A02151	PEELING SHIM FLAP STOP	EA	8	80.86	646.88	90
4	M81934/2-06C014	1BEARING,SLEEVE	EA	8	61.21	489.68	90

Grand Total : 1,292.71

Note:

1) Offer validity : 30 days from the date of quotation. Item quoted is subject to stock availability. ETA and lead time quoted is subject to changes

2) Terms of payment : To be made in full before delivery.

3) Cancellation : There will be 30% surcharge (imposed by AgustaWestland) for any cancellation

4) Delivery : Subject to prior sale

5) Condition : NEW/REPAIRED/OVERHAULED with Leonardo's Certification of Conformance / EASA certificate
6) Confirmation : Confirmation of availability of goods will be given within 5 working days upon receipt of the

: Confirmation of availability of goods will be given within 5 working days upon receipt of the official Purchase Order (PO) and customer's must respond to Kesuma Technology within

2 working days for confirmation of purchase.

Warranty period shall be as follows:

1) New condition : 12 months against manufacturer faults except for consumable items.

2) Repair condition : 6 months or 500 hrs against manufacturer faults

for KESUMA JECHNOLOGY SDN BHD