

KESUMA TECHNOLOGY SDN.BHD (Co No: 762152-X)

D-7-02, Capital 4, Oasis Square, No. 2, Jalan PJU 1A/7A, Ara Damansara, 47301 Petaling Jaya, Selangor Darul Ehsan, MALAYSIA. Tel : +603-7832 2998/7398 Fax : +603-7832 4998

(SST NO: B16-2207-32100006)

QUOTATION

T	

GALAXY AEROSPACE (M) SDN BHD	From	: Kasim Hj Ismail
79-1, 1st Floor, Jalan PJU 1A/41B, NZX Commercial Centre,		
Ara Damansara, 47301 Petaling Jaya, Selangor	Pages	: 01
Tel: +603-7887 0426	Date	: 11-May-2023
Faks: +603-7887 0526	Currency	: USD
Attn: Cik Nor Izzati Azmi / Cik Ashila Naja Mohd Zulkaple	AC Type/SN	: AW139
	Reference	: GALAXY116/05/2023
RE: SPARE OUOTATION		

QUOTATION

Below is the quotation for your RFQ: Email on 10/05/2023							
No	Part Number	Description	U.M	Qty	Unit Price	Total Price	Delivery Status
1	4611189010	SHAFT SHEAR	Ν	4	6,734.69	26,938.76	90
					Grand Total :	26,938.76	

Note:

1) Offer validity	: 30 days from the date of quotation. Item quoted is subject to stock availability. ETA and lead time quoted is subject to changes
Terms of payment	: To be made in full before delivery.
3) Cancellation	: There will be 30% surcharge (imposed by AgustaWestland) for any cancellation
4) Delivery	: Subject to prior sale
5) Condition	: NEW/REPAIRED/OVERHAULED with Leonardo's Certification of Conformance / EASA certificate
6) Confirmation	: Confirmation of availability of goods will be given within 5 working days upon receipt of the
	official Purchase Order (PO) and customer's must respond to Kesuma Technology within
	2 working days for confirmation of purchase.
4) Delivery 5) Condition	 Subject to prior sale NEW/REPAIRED/OVERHAULED with Leonardo's Certification of Conformance / EASA certificate Confirmation of availability of goods will be given within 5 working days upon receipt of the official Purchase Order (PO) and customer's must respond to Kesuma Technology within

Warranty period shall be as follows:

- 1) New condition
- : 12 months against manufacturer faults except for consumable items.
- 2) Repair condition
- : 6 months or 500 hrs against manufacturer faults

