

KESUMA TECHNOLOGY SDN.BHD

(Co No: 762152-X)

D-7-02, Capital 4, Oasis Square, No. 2, Jalan PJU 1A/7A, Ara Damansara, 47301 Petaling Jaya,

> Selangor Darul Ehsan, MALÂYSIA. Tel : +603-7832 2998/7398 Fax : +603-7832 4998

> > (SST NO: B16-2207-32100006)

: Kasim Hj Ismail

90

90

90

90

QUOTATION

To

GALAXY AEROSPACE (M) SDN BHD

79-1, 1st Floor, Jalan PJU 1A/41B, NZX Commercial Centre,

Ara Damansara, 47301 Petaling Jaya, Selangor

Tel: +603-7887 0426 Faks: +603-7887 0526

Attn: Cik Nor Izzati Azmi / Cik Ashila Naja Mohd Zulkaple

Below is the quotation for your RFQ: Email on 04/09/2023

Pages : 01

From

133.13

144.51

200.81

Date : 5-Sep-2023 Currency : **USD** AC Type/SN : **A109E**

133.13

144.51

200.81

Reference : GALAXY237/09/2023

RE: SPARE QUOTATION

109-0130-84-3

109-0130-83-3

109-0130-89-105

No	Part Number	Description	U.M	Qty	Unit Price	Total Price	Delivery Status
1	109-0130-97-103 (request P/N 109-0130-97-	LOCKING NUT	N	1	1,600.82	1,600.82	90
2	101) 109-0133-05-105 (request P/N 109-0133-05- 101)	T/R DUPLEX BEARING	N	1	7,642.25	7,642.25	90
3	129-0405-32-147	RING, LOCK	N	1	247.21	247.21	90
4	109-0130-28-103	WASHER,FLAT	N	1	109.49	109.49	90

Ν

Ν

Ν

MS17826-6 NUT,SELF- N 15 4.73 70.95

Grand Total: 10,149.17

Note:

5

6

7

8

1) Offer validity : 30 days from the date of quotation. Item quoted is subject to stock availability. ETA and lead time quoted is subject to changes

1

1

1

2) Terms of payment : To be made in full before delivery.

3) Cancellation : There will be 30% surcharge (imposed by AgustaWestland) for any cancellation

4) Delivery : Subject to prior sale

5) Condition

: NEW/REPAIRED/OVERHAULED with Leonardo's Certification of Conformance / EASA certificate

6) Confirmation

: Confirmation of availability of goods will be given within 5 working days upon receipt of the official Purchase Order (PO) and customer's must respond to Kesuma Technology within

2 working days for confirmation of purchase.

Warranty period shall be as follows:

1) New condition : 12 months against manufacturer faults except for consumable items.

BOOT, DUST AND UMIDITY SEAL

BOOT, DUST AND MSTRE SEAL

SPACER,RING

2) Repair condition : 6 months or 500 hrs against manufacturer faults

for KESUMA TECHNOLOGY SDN BHD