

## PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE JTC AVIATION 2 BUILDING #09-07 SELETAR AEROSPACE PARK

SINGAPORE www.precisionaviationgroup.com GST: 201737172D

## REPAIR / OVERHAUL QUOTE

For: Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD

Attn: MUZDALIFAH

SUITE 11-14, HELICOPTER CENTRE,

MALAYSIA INTERNATIONAL AEROSPACE CENTRE

SULTAN ABDUL AZIZ SHAH AIRPORT

**SUBANG 47200** MALAYSIA

Tel.: +60377347226

No. 5608240

Pg:1/1

Our Ref

797523

: SO# 5604920

: PO-24-7742 Your Ref

: PREPAID WIRE TRANSFR Terms Our Contact

: Ratan Pandey

eMail

Valid Until

Incoterms

: rpandey@heliparts.com : May-12-2024 : FCA - FREE CARRIER (ORIGIN) : Apr-12-2024

**Quote Date** 

Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
1	3059179-02 DATA COLLECTION UNIT ALT#: 32213-04 Serial No(s).: DP08-684 ECCN: 9A991.c Reported By Customer: Unit is INOP. Inspect and Advise Preliminary Inspection: Unit received in fair condition Unit passed functional test Unit will be retested and recertified Test and evaluation fee - USD 5,950.00  NOTE- This unit is on hold pending your faxed/emaany applicable taxes, freight or customs charges. T during the course of the repairs listed above. If add		thorization to proceed. Timate does not include airs are needed, we will co	his estimate doe ny add'l failures ntact you with a	s not include that may be found revised estimate.	\$ 5,950.00
				I	Sub Total:	\$ 5,950.00
	I BIN YA'AKOB,				Total: [USD]	\$ 5,950.00 ORIGINAL