



REPAIR INVOICE

MY AERO SPARES PLT (reg LLP0027219-LGN)

No 53-1 Jln Zuhai U5/179,
Seksyen U5 Star Avenue,
40150 Shah Alam, Selangor, Malaysia
sales@myaerospares.com | +603 7832 7109

INVOICE: 20220098

YOUR RO: RMN-24-1630

DATE: 04 JUNE 2024

BILL TO	SHIP TO	INSTRUCTIONS
GALAXY AEROSPACE (M) SDN BHD Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.	GALAXY AEROSPACE (M) SDN BHD Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. ATTN: Muzdalifah Hanani Roslizan Tel: +603-7455 0555	SHIP VIA: N/A ACCOUNT: N/A REMARKS: N/A

ITEM	PART NUMBER	DESCRIPTION	UNIT PRICE	TOTAL
01	7813-177-00-12	NR 2NTL INDICATOR SN: 700 <u>SHOP FINDING:</u> NO FAULT FOUND <u>ACTION:</u> UNIT PASSES ALL TEST - TEST AND RECERT TAT: 2-3 WEEKS DUAL RELEASE EASA/FAA	USD 1,680.00	USD 1,680.00

SUBTOTAL USD 1,680.00

TOTAL USD 1,680.00

Thank you for your business!

ITEM	PART NUMBER	DESCRIPTION	UNIT PRICE	TOTAL
		DUAL RELEASE EASA/FAA 12 Months warranty for Overhaul. 6 Months warranty for Repair.		
		FINAL PRICE FOR OVERHAUL OR FINAL PRICE FOR REPAIR	USD 3,337.00 USD 2,887.00	USD 3,337.00 USD 2,887.00

SUBTOTAL TBA

TOTAL TBA

Thank you for your business!



REPAIR INVOICE

MY AERO SPARES PLT (reg LLP0027219-LGN)

No 53-1 Jln Zuhail U5/179,
Seksyen U5 Star Avenue,
40150 Shah Alam, Selangor, Malaysia
sales@myaerospares.com | +603 7832 7109

INVOICE: 20220099

YOUR RO: RMN-24-1632

DATE: 04 JUNE 2024

BILL TO	SHIP TO	INSTRUCTIONS
GALAXY AEROSPACE (M) SDN BHD Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.	GALAXY AEROSPACE (M) SDN BHD Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. ATTN: Muzdalifah Hanani Roslizan Tel: +603-7455 0555	SHIP VIA: N/A ACCOUNT: N/A REMARKS: N/A

ITEM	PART NUMBER	DESCRIPTION	UNIT PRICE	TOTAL
01	7813-177-00-12	NR 2NTL INDICATOR SN: 702 <u>SHOP FINDING:</u> #2 POINTER STICKS, OUT OF CALIBRATION. <u>ACTION:</u> UNIT REQUIRE REPAIR. UNIT REQUIRES DISASSEMBLY, REPLACING POINTER #2, CLEANING, ALIGNMENT, CALIBRATION, TEST AND RECERT. TAT: 2-3 WEEKS DUAL RELEASE EASA/FAA 6 Months warranty	USD 5,281.00	USD 5,281.00

SUBTOTAL USD 5,281.00

TOTAL USD 5,281.00

Thank you for your business!