



TEARDOWN REPORT

3410 WEST MATHIS STREET
Lincoln, NE 68524
402.475.2611 - 800.562.6377
Fax: 402.479.4213
CRS#: JGVR194F

Attention

SUMAILI SULAIMAN

Customer

Galaxy Aerospace (M) Sdn Bhd *

Customer P.O.

MMA-24-1109

Payment Terms

Prepay - Wire

Fax#

Part#

071-01507-1301

Unit Description

TRANSPONDER CONTROL

Serial#

4462

Model

KFS-578A

Email

sumaili@galaxyaerospace.my

Work Order

KPQ1A

Work Order Description

TRANSPONDER CONTROL

Date

Sep 12, 2024

Registration#

M70-03

Reported Discrepancy

Discrepancy: Brightness found unserviceable and screen badly crazed

Inspection Findings

Preliminary Findings: Bench checked and duplicated discrepancy. Troubleshoot and found defective photocell and defective display filter.

Tech Notes

*** PRELIMINARY QUOTE ***

Quote valid for 30 days.

Thank you,
Tabbatha Goodman
Customer Account Representative I
Duncan Aviation Component Repairs
Office: 402-475-2611 ext 2611
Toll-Free: 800-562-6377

TOTALS SHOWN MAY NOT INCLUDE SALES TAX OR APPLICABLE PAYMENT FEES.

| | | |
|--|------------|---|
| Flat Rate Repair | | Salvage Part- Yes or No: Yes (Insert with lens) |
| Estimated Labor - List | \$596.00 | |
| Estimated Parts - List | \$3,000.00 | |
| Misc Charges | \$516.01 | |
| List Total | \$4,112.01 | |
| APPROVAL AUTHORIZATION SIGNATURE: | | |
| Date: _____ | | |

Should you decline the amount(s) above, the fee for this unit will be \$780.01

| |
|---------------------------|
| DECLINE SIGNATURE: |
| Date: _____ |



TEARDOWN REPORT

3410 WEST MATHIS STREET
Lincoln, NE 68524
402.475.2611 - 800.562.6377
Fax: 402.479.4213
CRS#: JGVR194F

Attention

SUMAILI SULAIMAN

Customer

Galaxy Aerospace (M) Sdn Bhd *

Customer P.O.

MMA-24-1109

Payment Terms

Prepay - Wire

Fax#

Part#

071-01507-1301

Unit Description

TRANSPONDER CONTROL

Serial#

4462

Model

KFS-578A

Email

sumaili@galaxyaerospace.my

Work Order

KPQ1A

Work Order Description

TRANSPONDER CONTROL

Date

Sep 12, 2024

Registration#

M70-03

Miscellaneous charges may include freight, loaner freight, sales taxes, recertification charges, hazardous waste, or any other charges outside normal parts and labor, and are subject to change. By signing this form, you consent that Duncan Aviation may use a fabricated part during the repair/overhaul of this unit.

Please sign one of the options above and return this fax (402.479.4213) or email to tabbetha.goodman@duncanaviation.com Thank you - Tabbetha Goodman