



Leonardo Malaysia Sdn Bhd
 Lot 1 & 2 , Helicopter Center,
 Sultan Abdul Aziz Shah Airport
 47200 Subang,
 Selangor Darul Ehsan, Malaysia

REPAIR QUOTATION

Leonardo Malaysia - Warehouse
 Lot 10, Jalan Teknologi, Taman Sains Selangor 1
 Kota Damansara, 47810 Petalín Jaya
 Selangor Darul Ehsan

CUSTOMER GALAXY (SUPERLYNX)	REPAIR QUOTATION FOR MATERIAL RELATED TO YOUR ORDER RMN-21-15	AW RMA	DATE 17.03.2022
		ISSUE N 400500247	OUR QUOTATION N. LM-0239
SHIP TO GALAXY (SUPERLYNX)	ON DATE 29.07.2021	TYPE OF CERTIFICATION	DATE 17.03.2022
	CONTACT	CUSTOMER CODE 50009236	CURRENCY GBP
	OFFER VALIDITY	SHIPPING METHOD	PAYMENT TERMS FDM2
	Incoterms Ex Works		

ITEM	SUPPLIABLE P/N - DESCRIPTION	UM	QUANTITY	S/N	UNIT PRICE	DISC %	TOTAL	ESTIMATED TAT DAY (*)
10	Part Number Received WG1451-0055-001 GENERATR,STARTER		N	Y10017	52,055.80			95
	Part Number to be Despatched WG1451-0055-001 GENERATR,STARTER							
	WORK DETAIL : REPAIR							
	ACTIVITIES PRICE						52,055.80	
<p>(*) TAT calculation starts when the returned components is received, evaluated and considered eligible for repair, or from the acceptance of Leonardo Helicopter proposal by the Customer whichever occurs last. The above is not applicable if regulated by prior agreements executed between the Customer and Leonardo Helicopters . Shipping Methods : Payment Terms : FDM2 - 60days Billing Date This quotation is definitive , a revised repair quotation will be issued in case : - during the repair activity it is nessasary to perform additional work or to replace other components not estimated at this stage Note : WE ARE WAITING FOR YOUR APPROVAL WORK REQUIRED : REPAIR</p>								