

CABIN REFURBISHMENT PROPOSAL

TO



maintenance.repair.overhaul

FOR

NAVY

AIRCRAFT REG.: M502-1

AIRCRAFT MSN: TBA

Proposal Ref : GA/0903/M5021/01

Rev. : 0

Date : 2 SEPT 2020

Prepared By K. Uvarajasingam

Page : Cover

E. PAYMENT TERMS

The quote based on the below payment schedule; 60% deposit upon Confirmation with P.O. 40% upon completion of the refurbishment in aircraft.

F. WARRANTY

Paviation guarantees that the supplied product will be free of defects in design, materials and workmanship for a period of **Twelve (12) months** after delivery.

G. EXPIRATION OF QUOTATION

This quote is valid until 31 October 2020.

Proposal Ref : GA/0903/M5021/01

Rev. : 0

Date : 2 SEPT 2020

Prepared By K. Uvarajasingam

Page : 2 of 2

A. INTRODUCTION

Pecca Aviation Services Sdn Bhd (Paviation) is pleased to provide a proposal for Cabin Refurbishment

GALAXY AEROSPACE (M) SDN BHD (GA)

B. WORK SCOPE

The work scope for the cabin refurbishment listed as below;

- 1) Seat Cover Repair (Pilot, Co-pilot, 4 passenger seats)
- 2) Bottom Seat Pan with non aviation PVC replacement.

The work scope doesn't include the removal & re-installation of the seats and components from aircraft

C. INSPECTION

As per inspection by Pecca Aviation Team.







D. PRICE TABLE

All price are quoted in Malaysian Ringgit (MYR) and inclusive of materials, labour and transportation of Component to GA Hangar.

D.1 Seat Cover Repair

epair and refurbishment of 4 Passenger Seats and 2 Pilot Seats		
Estimate Cycle Time	: 4 days	RM7,000.00

D.2 Changing with non aviation PVC

Bottom Seat Pan		
Cycle time	: 3 days	RM2,000.00
- 4-8 - 10 i		

Grand Total

RM9,000.00

Proposal Ref : GA/0903/M5021/01

Rev. : 0

Date : 2 SEPT 2020

Prepared By K. Uvarajasingam

Page : 1 of 2