



## PBA Technology Pte Ltd

505 Yishun industrial Park A PBA Building Singapore 768733  
Tel: +65 65766760 Fax: +65 65766761  
Web: www.pbatechnology.com Email: enquiry@pbatechnology.com  
Reg. No 199004231G GST No. M2-0095113-1

### Invoice

Order No. PF1700492

Date: 18-Aug-2017

Attend by: Jean Leong

Date Promised

Order Ref: GAM/PO/17/064

*Customer:*

**GALAXY AEROSPACE (M) SDN BHD**

79-1,1ST FLOOR, JLN PJU 1A/41B

NZX COMMERCIAL CENTRE,

ARA DAMANSARA,

47301 PETALING JAYA,

SELANGOR,

Malaysia

Tel: +603-7887-0426

Fax: +603-7887-0526

Attn: HAZRIN SANI

*Ship To:*

**GALAXY AEROSPACE (M) SDN BHD**

79-1,1ST FLOOR, JLN PJU 1A/41B

NZX COMMERCIAL CENTRE,

ARA DAMANSARA,

47301 PETALING JAYA,

SELANGOR,

Malaysia

All prices are in USD

No.	Product	Qty	UoM	Unit Price	Line Net
1	COOLSPool 58 PORTABLE GPU	2	EA	4,890.00	9,780.00
2	ASPA-PS-MODULE-50AMPS 50AMP MODULE (SET 28V NOMINAL)	1	EA	2,500.00	2,500.00
3	ASPA-LEAD-3METRE NATO-3 METRE AVIATION LEAD WITH NATO PLUG	2	EA	395.00	790.00
				Sub Total	13,070.00
				Zero-rated	0.00
				Grand Total	13,070.00

Freight Term: Self-collection

Payment Terms: T/T Advance Payment

Remarks: "THIS IS AN AIRCRAFT PARTS / COMPONENT"

#### CERTIFICATE OF CONFORMANCE

It is hereby certified that item(s) furnished on this invoice/delivery order have been visually inspected and conform with current governmental and manufacturer's requirement, specifications and drawings based on information supplied to us by the respective parties. Inspection records are on file at this facility and available for review on request.

This certificate has been produced electronically and is valid without a signature.

E. & O. E.

Any claims for shortages or adjustments must be made within ten (10) days from receipt of Goods. Claims for Damaged Products, Suspected Damages within the carton or carton shortages on delivery must be so noted on the Bill of Lading or Shipping Papers, Any Freight Claims must be filed directly with the carrier as PBA Technology will not be liable for Damage or Loss caused to the Shipment by common carrier. In the event of such claim, the customer shall be required to make timely payment to PBA Technology for any amount due. Authorizations must be obtained from PBA Technology before any products can be returned for credit or replacement

For payment exceeding the specified payment terms, interest will be charge at 1% per month