



# PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE  
 JTC AVIATION 2 BUILDING #09-07  
 SELETAR AEROSPACE PARK  
 65-6817-3370

797523  
 SINGAPORE  
 www.precisionaviationgroup.com  
 GST: 201737172D

## REPAIR / OVERHAUL QUOTE

For : Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD  
 Attn: NUR AFRINA AZHAR KHAN  
 SUITE 11-14, HELICOPTER CENTRE,  
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE  
 SULTAN ABDUL AZIZ SHAH AIRPORT  
 SUBANG 47200  
 MALAYSIA  
 Tel. : +603-7455 0555

<b>No. 5606730</b>	Pg:1/1
--------------------	--------

Our Ref : SO# 5604187  
 Your Ref : MMA-23-684  
 Terms : PREPAID WIRE TRANSFR  
 Our Contact : Ratan Pandey  
 eMail : rpandey@heliparts.com  
 Valid Until : Aug-12-2023  
 Incoterms : FCA - FREE CARRIER (ORIGIN)  
 Quote Date : Aug-07-2023

Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
1	<b>524-031</b> STARTER GENERATOR <b>ALT#:</b> 704A46101011 <b>Serial No(s):</b> 5174 <b>ECCN:</b> 9A991  Reported By Customer: UNIT REQUIRES OVERHAUL, INSPECT AND ADVISE  Preliminary Inspection: Unit received in bad condition Unit failed incoming tests T-block cover missing, requires replacement USD 495.00 Screen detached from fan cover,requires replacement USD1,895.00 Armature found corroded, deemed BER. Requires replacement \$3,950.00 Stator failed Hi-pot testing, requires rework USD 1,750.00 Unit requires replacement of parts and standard overhaul Standard overhaul USD 4,250.00  Corrective Action: UNIT WILL BE OVERHAULED AS PER CMM, TESTED AND RECERTIFIED.  NOTE- This unit is on hold pending your faxed/emailed authorization to proceed. This estimate does not include any applicable taxes, freight or customs charges. This estimate does not include any add'l failures that may be found during the course of the repairs listed above. If add'l repairs are needed, we will contact you with a revised estimate.  Approval Signature: _____ Date: _____	OH	1 EA	55 Days	\$ 12,340.00 EA	\$ 12,340.00

					<b>Sub Total:</b>	\$ 12,340.00
					<b>Total:</b>	[USD] \$ 12,340.00