



# PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE  
 JTC AVIATION 2 BUILDING #09-07  
 SELETAR AEROSPACE PARK  
 65-6817-3370

797523  
 SINGAPORE  
 www.precisionaviationgroup.com  
 GST: 201737172D

## EXCHANGE QUOTE



Print Date : Jan-25-2023 12:09 AM

Printed By : RIDZUAN BIN YA'AKOB Print No. : 3

**For : Account No. [GALAXYMY]**

**No. 5605709**

Pg:1/2

GALAXY AEROSPACE (M) SDN BHD  
 Attn: NUR AFRINA AZHAR KHAN  
 SUITE 11-14, HELICOPTER CENTRE,  
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE  
 SULTAN ABDUL AZIZ SHAH AIRPORT  
 SUBANG 47200  
 MALAYSIA  
 Tel. : +603-7455 0555

**Our Ref** : Q5605709  
**Terms** : PREPAID WIRE TRANSFR  
**Our Contact** : Ratan Pandey  
**eMail** : rpandey@heliparts.com  
**Valid Until** : Feb-23-2023  
**Incoterms** : FCA - FREE CARRIER (ORIGIN)  
**Quote Date** : Jan-25-2023

In response to your request, we are pleased to quote you the following:

Line	P/N & Description	Cn	Qty Bid	Delivery	Unit Price	Amount
1	90-380001-23 MASTER CYLINDER ALT#: CM1000-23 MFG: (RAPID*) BEEHCRAFT - WICHITA Note: ** Exchange Charge- Core Return Required **	SV	2 EA	5 Days	\$ 595.00 EA	\$ 1,190.00
2	90-380001-23 MASTER CYLINDER ALT#: CM1000-23 MFG: (RAPID*) BEEHCRAFT - WICHITA Note: ** Core Charge [ \$ 350.00 ]**	AR	2 EA	Stock		
3	90-380001-23 MASTER CYLINDER ALT#: CM1000-23 MFG: (RAPID*) BEEHCRAFT - WICHITA Note: OUTRIGHT PRICE  Certification Type: FAA8130  Exchange Policy  Exchange prices are based on the customer returning a repairable core of the same part number. PAG reserves the option to reject any returned unit that has been damaged from abnormal causes, such as fire, crash, submersion, cannibalization, unauthorized repair or excessive wear. Units found to be economically non-repairable will be returned. Cost of any repair above normal charges which is found, either at the time of the exchange or later during overhaul, will be billed in addition to the exchange or later during overhaul. If an acceptable core is not received within 30 days of date of invoice, the applicable core charge will be due.	NE	2 EA	3 Days	\$ 895.00 EA	\$ 1,790.00

Continued on next page...



# PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE  
 JTC AVIATION 2 BUILDING #09-07  
 SELETAR AEROSPACE PARK  
 65-6817-3370

797523  
 SINGAPORE  
[www.precisionaviationgroup.com](http://www.precisionaviationgroup.com)  
 GST: 201737172D

## EXCHANGE QUOTE



Print Date : Jan-25-2023 12:09 AM

Printed By : RIDZUAN BIN YA'AKOB Print No. : 3

Our Ref : Q5605709

Quotation No. 5605709 Page :2/2

Line	P/N & Description	Cn	Qty Bid	Delivery	Unit Price	Amount
	<p>All units quoted are subject to prior sale</p> <p>Freight: The shipping of all core returns and repairs to PAG is the sole responsibility of the customer. Any costs incurred by PAG including freight, Dangerous goods, customs clearance or delivery fees will be recharged to the customer.</p>					

					<b>Sub Total:</b>	\$ 2,980.00
					<b>Total:</b>	[USD] \$ 2,980.00

RIDZUAN BIN YA'AKOB,