

PRECISION HELIPARTS SINGAPORE PTE LTD

690 WEST CAMP ROAD SINGAPORE JTC AVIATION 2 BUILDING #09-07 SELETAR AEROSPACE PARK 65-6817-3370

SINGAPORE www.precisionaviationgroup.com GST: 201737172D

EXCHANGE QUOTE

2:35 AM



Print No. :

Pg:1/1

Printed By: RIDZUAN BIN YA'AKOB

For: Account No. [GALAXYMY]

GALAXY AEROSPACE (M) SDN BHD Attn: NUR AFRINA AZHÀR KHAN

SUITE 11-14, HELICOPTER CENTRE, MALAYSIA INTERNATIONAL AEROSPACE CENTRE

SULTAN ABDUL AZIZ SHAH AIRPORT

SUBANG 47200 MALAYSIA

Print Date: Nov-16-2022

Tel.: +603-7455 0555

In response to your request, we are pleased to quote you the following:

No. 5605419

Our Ref

: Q5605419

Terms :PREPAID WIRE TRANSFR

Our Contact : Ratan Pandey

: rpandey@heliparts.com : Dec-16-2022 eMail

Valid Until

: FCA - FREE CARRIER (ORIGIN) Incoterms

Quote Date : Nov-16-2022

Line	P/N & Description	Cn	Qty Bid	Delivery	Unit Price	Amount				
1	300-0271-1 BLOWER ASSY AFT EVAP ALT#: 300-0271-1 MFG: (RAPID*) BEECHCRAFT - WICHITA	ОН	1 EA	5 Days	\$ 8,750.00 EA	\$ 8,750.00				
2	Note: ** Exchange Charge- Core Return Required 300-0271-1 BLOWER ASSY AFT EVAP ALT#: 300-0271-1 MFG: (RAPID*) BEECHCRAFT - WICHITA Note: ** Core Charge USD4,000.00 **	** AR	1 EA	Stock						
	Certification Type: FAA8130 Exchange Policy									
	Exchange prices are based on the customer returning a repairable core of the same part number. PAG reserves the option to reject any returned unit that has been damaged from abnormal causes, such as fire, crash, submersion, cannibalization, unauthorized repair or excessive wear. Units found to be economically non-repairable will be returned. Cost of any repair above normal charges which is found, either at the time of the exchange or later during overhaul, will be billed in addition to the exchange or later during overhaul. If an acceptable core is not received within 30 days of date of invoice, the applicable core charge will be due.									
	All units quoted are subject to prior sale Freight: The shipping of all core returns and repairs to PAG is the sole responsibility of the customer. Any costs incurred by PAG including freight, Dangerous goods, customs clearance or delivery fees will be recharged to the customer.									
					Sub Total:	\$ 8,750.00				

will be reditalged to the oddt	omor.			
		Sub Tota	al:	\$ 8,750.00
				·
		Total:	[USD]	\$ 8,750.00
RIDZUAN BIN YA'AKOB,			[]	Ψ 3,1 33.03