

## THERMAL SPRAY & MANUFACTURING TECHNOLOGY SDN BHD

No. 14 JALAN UTARID U5/21 (PS), SEKSYEN U5 PANASURIA, 40150 SHAH ALAM, SELANGOR. (HQ)
LOT 34094, TGKT BWH, KG PADANG TEPOH, JLN KELANTAN, 21060 KUALA NERUS, TERENGGANU (BRANCH)
TEL:03-78474171 FAX:03-78468968 E-MAIL: thermal\_spraysb@yahoo.com



Galaxy Aerospace (M) Sdn Bhd Suite 11-14, MRO Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor.

KE	AIZED	QUO	ΙΑΙ	ION

No.: GA01/23

Date: 23/05/2023

Terms of Payment: As Below

Validity: 15 Days

Item No.	Description	Quantity (Unit)	Unit Price (RM/Unit)	Amount (RM)
1	To repair and welding on crack aluminum fuel tank consist of: a) Remove sealent and soap cleaning inside tank b) NDT dye panatrant pre c) Tig welding defect area by using filler rod ER5356 d) NDT dye penatrend post e) Repaint repair area by using yellow 487 Primer and Epoxy P20 top coat (special paint for tank)	1 1 1 1	800.00 300.00 1,250.00 300.00 3,500.00	800.00 300.00 1,250.00 300.00 3,500.00
	Note: - Deposit 50% After Receive Order			
	- Balance 50% After 30 days			6,150.00

We hope the above price will meet your kind consideration and looking forward to your favorable reply.

Above quotation accepted by	TSMT Sdn. Bhd.
	Zulkíflí Ismaíl
(Chop & Sign)	Authorised Signature