

PRIME INDUSTRIES, INC.

406 Dividend Drive

Peachtree City, GA 30269

Tel: (770) 632-1851

UNITED STATES Fax: (770) 632-1852

www.primeindustriesusa.com

FEIN 65-1020927



EXCHANGE QUOTE

2:17 PM

Printed By: Marc Lacourly Print No.: 1

For : Account No. [GALAXY]

GALAXY AEROSPACE (M) SDN BHD

Attn: Nor Azman Huzir, Support & Logistics Manager

SUITE 11-14, HELICOPTER CENTER

MALAYSIA INTERNATIONAL AEROSPACE CENTRE

SULTAN ABDUL AZIZ SHAH AIRPORT

SELANGOR, SUBANG 47200

MALAYSIA

Print Date : Jun-19-2020

Tel.: 011 603 7887 0426 Fax: 011 603 7887 0526

In response to your request, we are pleased to quote you the following:

No. 111032

Pg:1/2

Our Ref : 111032-ML End-User : KING AIR KA350 Terms : NET-15 DAYS Our Contact : Marc Lacourly

eMail : mlacourly@primeindustriesusa.com

Valid Until : Jul-19-2020 F.O.B. : EX-WORKS Quote Date : Jun-19-2020

622-5027-101					
SERVO ELEVATOR ACTUATOR I/W: SVO-85B	SV	1 EA	3 Days	\$ 2,500.00000 EA	\$ 2,500.00
Tag Info: FRESH 2020 FAA/EASA MFG: (13499) ROCKWELL COLLINS INC					
		ete and normal core ** 1 EA	15 Days	\$ 500.00000 EA	* No Charge *
MFG: (13499) ROCKWELL COLLINS INC Note: ** Core Value ** 622-5029-102 SERVO MOUNT	ОН	1 EA	2 Days	\$ 2,500.00000 EA	\$ 2,500.00
I/W: SMT-85B Tag Info: FRESH 2020 FAA/EASA MFG: (13499) ROCKWELL COLLINS INC					
o o		ete and normal core ** 1 EA	15 Days	\$ 500.00000 EA	* No Charge *
MFG: (13499) ROCKWELL COLLINS INC Note: ** Core Value **					
	I/W: SVO-85B Tag Info: FRESH 2020 FAA/EASA MFG: (13499) ROCKWELL COLLINS INC Note: ** Flat Exchange Charge with the return of a 622-5027-101 SERVO ELEVATOR ACTUATOR I/W: SVO-85B MFG: (13499) ROCKWELL COLLINS INC Note: ** Core Value ** 622-5029-102 SERVO MOUNT I/W: SMT-85B Tag Info: FRESH 2020 FAA/EASA MFG: (13499) ROCKWELL COLLINS INC Note: ** Flat Exchange Charge with the return of a 622-5029-102 SERVO MOUNT I/W: SMT-85B MFG: (13499) ROCKWELL COLLINS INC	I/W: SVO-85B Tag Info: FRESH 2020 FAA/EASA MFG: (13499) ROCKWELL COLLINS INC Note: ** Flat Exchange Charge with the return of a 622-5027-101 SERVO ELEVATOR ACTUATOR I/W: SVO-85B MFG: (13499) ROCKWELL COLLINS INC Note: ** Core Value ** 622-5029-102 SERVO MOUNT I/W: SMT-85B Tag Info: FRESH 2020 FAA/EASA MFG: (13499) ROCKWELL COLLINS INC Note: ** Flat Exchange Charge with the return of a 622-5029-102 SERVO MOUNT I/W: SMT-85B MFG: (13499) ROCKWELL COLLINS INC	I/W: SVO-85B Tag Info: FRESH 2020 FAA/EASA MFG: (13499) ROCKWELL COLLINS INC Note: ** Flat Exchange Charge with the return of a complete and normal core ** AR 1 EA SERVO ELEVATOR ACTUATOR I/W: SVO-85B MFG: (13499) ROCKWELL COLLINS INC Note: ** Core Value ** 622-5029-102 SERVO MOUNT I/W: SMT-85B Tag Info: FRESH 2020 FAA/EASA MFG: (13499) ROCKWELL COLLINS INC Note: ** Flat Exchange Charge with the return of a complete and normal core ** AR 1 EA SERVO MOUNT I/W: SMT-85B MFG: (13499) ROCKWELL COLLINS INC	I/W: SVO-85B Tag Info: FRESH 2020 FAA/EASA MFG: (13499) ROCKWELL COLLINS INC Note: ** Flat Exchange Charge with the return of a 622-5027-101 SERVO ELEVATOR ACTUATOR I/W: SVO-85B MFG: (13499) ROCKWELL COLLINS INC Note: ** Core Value ** 622-5029-102 SERVO MOUNT I/W: SMT-85B Tag Info: FRESH 2020 FAA/EASA MFG: (13499) ROCKWELL COLLINS INC Note: ** Flat Exchange Charge with the return of a 622-5029-102 SERVO MOUNT I/W: SMT-85B Tag Info: FRESH 2020 FAA/EASA MFG: (13499) ROCKWELL COLLINS INC Note: ** Flat Exchange Charge with the return of a 622-5029-102 SERVO MOUNT I/W: SMT-85B MFG: (13499) ROCKWELL COLLINS INC	I/W: SVO-85B Tag Info: FRESH 2020 FAA/EASA MFG: (13499) ROCKWELL COLLINS INC Note: ** Flat Exchange Charge with the return of a 622-5027-101 SERVO ELEVATOR ACTUATOR I/W: SVO-85B MFG: (13499) ROCKWELL COLLINS INC Note: ** Core Value ** 622-5029-102 SERVO MOUNT I/W: SMT-85B Tag Info: FRESH 2020 FAA/EASA MFG: (13499) ROCKWELL COLLINS INC Note: ** Flat Exchange Charge with the return of a 622-5029-102 SERVO MOUNT I/W: SMT-85B Tag Info: FRESH 2020 FAA/EASA MFG: (13499) ROCKWELL COLLINS INC Note: ** Flat Exchange Charge with the return of a 622-5029-102 SERVO MOUNT I/W: SMT-85B MFG: (13499) ROCKWELL COLLINS INC

- 1. Prime Industries' Standard Terms & Conditions of Sale apply. Delivery is quoted in Business Days only,
- 2. Prices & deliveries herein quoted are applicable to the quantities as covered by this quotation.
- 3. All materials quoted from stock or with deliveries of 15 days or less are subject to prior sale.
- 4. In the event of an order, the above commodities are not to be shipped to any country that has an embargo placed against it by the U.S. Government. Should these commodities require an export license, it shall be your responsibility to comply with the United States Department of State/Commerce Export Regulations.
- 5. If an Export License is required, a \$250.00 processing fee will apply for each occurrence
- 6. Hazardous Material (HAZMAT) Shipments shall be subject to a minimum Haz-Mat handling fee of \$250.00 per package.

FN=Factory New/NS=New Surplus/OH=Overhaul Certified/SV=Serviceable/RP=Repaired/AR=As Removed

Continued on next page...



Print Date : Jun-19-2020

XCHANGE QUOTE

2:17 PM

PRIME INDUSTRIES, INC.

406 Dividend Drive

Traffic in Arms Regulations (ITAR) and/or the Export Administration Regulations (EAR). Without the proper approval from the U.S. Department of State or the U.S. Department of Commerce, the transfer

or release of this technical data to a foreign person or entity whether manufactured within the

Peachtree City, GA 30269 Tel: (770) 632-1851 UNITED STATES
Fax: (770) 632-1852

www.primeindustriesusa.com

FEIN 65-1020927



Our Ref Ref3 Ref1 Fin.Dest. Quotation No. 111032 Page: 2/2 Your Ref. Ref2 End-User Ref4 Line P/N & Description Cnd Qty Bid Delivery **Unit Price Amount EXPORT COMPLIANCE STATEMENT** Products sold by PRIME INDUSTRIES, INC. may require a license from the U.S. Department of State, the U.S. Department of Commerce, or the U.S. Department of Treasury to be exported/shipped out of the United States. PRIME INDUSTRIES, INC. is committed to strict compliance with all applicable United States Export Control Regulations including (but not limited to) the International Traffic in Arms Regulations (ITAR), the Export Administration Regulations (EAR), Office of Foreign Assets Control (OFAC), and the Foreign Corrupt Practices Act (FCPA). The export and re-export of products requiring a license from the U.S. Department of State, the U.S. Department of Commerce, and/or the U.S. Department of Treasury is strictly prohibited. Additionally, PRIME INDUSTRIES, INC. correspondence may contain technical data that is dontrolled and compliant with the International

THANK YOU FOR YOUR ORDER

United States or abroad, is strictly prohibited.

- · -	
Sub T	<u>Fotal: \$ 5,000.00</u>
. Prime Industries' Standard Terms & Conditions of Sale apply. Delivery is quoted in Business Days only,	
Prices & deliveries herein quoted are applicable to the quantities as covered by this quotation.	
. All materials quoted from stock or with deliveries of 15 days or less are subject to prior sale.	
. In the event of an order, the above commodities are not to be shipped to any country that has an embargo	
placed against it by the U.S. Government. Should these commodities require an export license, it shall be	

5. If an Export License is required, a \$250.00 processing fee will apply for each occurrence

6. Hazardous Material (HAZMAT) Shipments shall be subject to a minimum Haz-Mat handling fee of \$250.00 per package.

FN=Factory New/NS=New Surplus/OH=Overhaul Certified/SV=Serviceable/RP=Repaired/AR=As Removed

your responsibilty to comply with the United States Department of State/Commerce Export Regulations.

removea				
	Total:	[USD]	\$ 5,000.00	