

PRIME INDUSTRIES, INC.

406 Dividend Drive

Peachtree City, GA 30269 Tel: (770) 632-1851

UNITED STATES
Fax: (770) 632-1852

www.primeindustriesusa.com

REPAIR & OVERHAUL QUOTE



Printed By : Marc Lacourly Print No. : 7

For: Account No. [GALAXY REP]

4:57 PM

GALAXY AEROSPACE (M) SDN BHD Attn: NUR SYAMIM SYUHADA AMDAN SUITE 11-14 HELICOPTER CENTRE MALAYSIA INTL AEROSPACE CENTRE SULTAN ABDUL AZIZ SHAH AIRPORT

SUBANG SELANGOR 47200

MALAYSIA

Print Date : Jul-18-2022

Tel.: 603 77347226 Fax: 603 60377347526

In response to your request, we are pleased to quote you the following:

No. 117058

Pg:1/3

Our Ref : 117058-ML Your Ref. : RMN-22-302 Fin.Dest. : MALAYSIA

End-User : GALAXY AEROSPACE Terms : NET-30 DAYS

Our Contact : KIMBERLY CHANCE eMail : KIMBERLY@PRIMEINDUSTRIESUSA.COM

Valid Until : Aug-17-2022
F.O.B. : EX-WORKS
Quote Date : Jul-18-2022
Our S.O. : 041055
Cust P.O. : RMN-22-302

Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
1	355A32-0600-06M BEVEL REDUCTION GEARBOX I/W: 355A32-0600-06 ECCN: 9A991 Serial No(s).: M5862 Serial No.: M5862 Trace To: LOG CARD MFG: (F0210) AIRBUS HELICOPTERS Note: REPAIR QUOTE	SV	1 EA	45 Days	\$ 35,705.00000 EA	\$ 35,705.00
2	350A32-0110-00 EPICYCLIC REDUCTION GEAR I/W: 350A32-0110-00M Serial No.: M6729 MFG: (F0210) AIRBUS HELICOPTERS	SV	1 EA	45 Days	\$ 3,083.50000 EA	\$ 3,083.50
3	355A32-0210-02 GEARBOX COMBINER Serial No.: M369 MFG: (F0210) AIRBUS HELICOPTERS PRIME PO NUMBER: 051213	SV	1 EA	45 Days	\$ 19,250.00000 EA	\$ 19,250.00
						i

Continued on next page...



PRIME INDUSTRIES, INC.

406 Dividend Drive Peachtree City, GA 30269

Tel: (770) 632-1851

UNITED STATES Fax: (770) 632-1852 www.primeindustriesusa.com



REPAIR & OVERHAUL QUOTE

Print Date	: Jul-18-2022 4:57 PM				Printed By : Mar	c Lacourly Print No. : 7
our Ref Our Ref.	: 117058-ML : RMN-22-302	Fin.Dest. End-User	: MALAYSIA : GALAXY AERO!	SPACE	Quotation No. 1	17058 Page : 2/3
Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount
	PN: 355A32-0600-06 SN: M5862					
	EVALUATIONS/FINDINGS: IN ADDITION TO					
	SPACER, HALF. HOUSING REQUIRES REP					PER AND LOWER FLAN
	BOLT HOLES. REPAIR LOWER FLANGE UP	PPER SURF	ACE WTH SHIM. \$34,47	8.00 (PHOTOS	IN EMAIL)	
	PN: 355A32-0210-02 SN: M369					
	EVALUATIONS/FINDINGS: IN ADDITION TO					
	PARTS: BOLTS, FLANGE SUPPORTS, NUT	S, PINS, CC	UPLING DISCS, WASH	ERS AND FLEC	TOR WASHERS. \$19,25	0.00 (PHOTOS IN EMAIL
	PN: 350A32-0110-00 SN: M6729		 	DOLTO 1001		10.054511.4115
	EVALUATIONS/FINDINGS: UNIT REQUIRED	REPAIR A	ND REPLACEMENT OF	BOLIS, LOCK	PLATES AND NUTS. RIN	IG GEARN AND
	WASHER RE-PAINTED. \$3,083.50					
	CONDITION AFTER COMPLETION DEDAIR	NED				
	CONDITION AFTER COMPLETION: REPAIR	(ED				
	TOTAL QUOTE: \$ 56,811.50					
	TURN AROUND TIME (DAYS): 45 DAYS					
	TURN AROUND TIME (DATS). 43 DATS					
	APPROVAL SIGNATURE:	- ΓΔ	 TE:			
	ALT ROVAL SIGNATORE.		·			
	NAME:					
	EXPORT COMPLIANCE STATEMENT					
	Products sold by PRIME INDUSTRIES, INC. r	may require	a license from the U.S. D	 epartment of St	ate,	
				I		
					Continued or	n next page
						. 5



PRIME INDUSTRIES, INC.

406 Dividend Drive Peachtree City, GA 30269

Tel: (770) 632-1851

UNITED STATES
Fax: (770) 632-1852
www.primeindustriesusa.com



REPAIR & OVERHAUL QUOTE

Print Date: Jul-18-2022 4:57 PM

Our Ref: 117058-ML Fin.Dest. : MALAYSIA Quotation No. 117058 Page: 3/3
Your Ref. : RMN-22-302 End-User : GALAXY AEROSPACE

Line	P/N & Description	Cnd	Qty Bid	Delivery	Unit Price	Amount	
	the U.S. Department of Commerce, or the U.S. Dep	artme	nt of Treasury to be expo	rted/shipped			
	out of the United States. PRIME INDUSTRIES, INC	is co	mmitted to strict complia	ce with all appli	cable		
	United States Export Control Regulations including	(but no	ot limited to) the Internati	onal Traffic			
	in Arms Regulations (ITAR), the Export Administrati	ion Re	gulations (EAR), Office o	f Foreign			
	Assets Control (OFAC), and the Foreign Corrupt Pr	actices	Act (FCPA). The export	and re-export			
	of products requiring a license from the U.S. Depart	tment o	of State, the U.S. Departi	nent of Commer	ce,		
	and/or the U.S. Department of Treasury is strictly pr	rohibite	d. Additionally, PRIME I	NDUSTRIES, IN	C.		
	correspondence may contain technical data that is	ontrol	led and compliant with th	e International			
	Traffic in Arms Regulations (ITAR) and/or the Expo	rt Adm	inistration Regulations (E	AR). Without the	e		
	proper approval from the U.S. Department of State or the U.S. Department of Commerce, the transfer						
	or release of this technical data to a foreign person	or enti	ty whether manufactured	within the			
	United States or abroad, is strictly prohibited.						
	THANK YOU FOR YOUR ORDER						
					Sub Total:	\$ 58,038.50	
	1/1.10						
	Mylleger						
100		Total: [USD]	\$ 58,038.50				
KYLE BEAMAN, Rep & OH Div Manager Conscients (a) DENTA CON 3222C of transport							