

PRIME INDUSTRIES, INC.

406 Dividend Drive

Peachtree City, GA 30269

Tel: (770) 632-1851

UNITED STATES
Fax: (770) 632-1852
www.primeindustriesusa.com



REPAIR & OVERHAUL QUOTE

Print Date: Apr-25-2024 4:48 PM Printed By: Marc Lacourly Print No.: 2

For: Account No. [GALAXY REP]

GALAXY AEROSPACE (M) SDN BHD Attn: MUZDALIFAH ROSLIZAN SUITE 11-14 HELICOPTER CENTRE MALAYSIA INTL AEROSPACE CENTRE SULTAN ABDUL AZIZ SHAH AIRPORT SUBANG SELANGOR 47200

MALAYSIA

Tel.: 603 77347226 Fax: 603 60377347526

In response to your request, we are pleased to quote you the following:

No. 123698

Pg:1/3

Our Ref : 123698-ML
Your Ref. : RMN-24-1591
Fin.Dest. : MALAYSIA
Terms : NET-30 DAYS
Our Contact : KIMBERLY CHANCE

eMail : <u>KIMBERLY@PRIMEINDUSTRIESUSA.COM</u>

Valid Until : May-25-2024 F.O.B. : EX-WORKS Quote Date : Apr-25-2024 Our S.O. : 046722 Cust P.O. : RMN-24-1591

| Line | P/N & Description | Cnd | Qty Bid | Delivery | Unit Price | Amount |
|------|---|-------|----------------------|-------------|-------------------------|------------------|
| 1 | 355A61-5210-0401 | RP | 1 EA | 21 Days | \$ 2,335.00000 EA | \$ 2,335.00 |
| | PCB,7ALPHA1 Serial No(s).: FAS30058 | | | | | |
| | Serial No.: FAS30058 | | | | | |
| | MFG: (F0210) AIRBUS HELICOPTERS | | | | | |
| | Note: REPAIR QUOTE | | | | | |
| | PRIME PO NUMBER: 057118 | | | | | |
| | UNIT MISUSED: NO | | | | | |
| | EVALUATIONS/FINDINGS: UNIT EVALUATED FO | R REF | PAIR. DISCREPANCY IS | CONFIRMED, | 5 PIN MTA B IS BURNT, I | REQUIRES |
| | REPLACEMENT. CIRCUIT BOARD UNDER CONN | ECTC | R B IS BURNED AND R | EQUIRES REP | AIR. REQUIRES INSPEC | TION AND ALL |
| | QUESTIONABLE SOLDER JOINTS WILL REQUIR | E RE- | SOLDERING. CONFORM | MAL COATING | WIL BE APPLIED AS NEE | DED. UNIT PASSED |
| | INITIAL TESTING. | | | | | |
| | CONDITION AFTER COMPLETION: REPAIRED | | | | | |
| | EXCLUSIONS: | | | | | |
| | | | | | | |
| | FLAT RATE: \$ | | | | | |
| | TOTAL QUOTE: \$ 2,335.00 | | | | | |
| | EVALUATION FEE IF QUOTE DENIED: \$ | | | | | |

- 1. Prime Industries' Standard Terms & Conditions of Sale apply, see WWW.PRIMEINDUSTRIESUSA.COM.
- 2. Prices & deliveries are quoted in business day and are applicable to the quantities as covered by this quotation.
- 3. All materials quoted from stock or with deliveries of 15 days or less are subject to prior sale.
- 4. In the event of an order, the above commodities are not to be shipped to any country that has an embargo placed against it by the U.S. Government. Should these commodities require an export license, it shall be your responsibility to comply with the United States Department of State/Commerce Export Regulations.
- 5. If an Export License is required, a \$250.00 processing fee will apply for each occurrence
- 6. Hazardous Material (HAZMAT) Shipments shall be subject to a minimum Haz-Mat handling fee of \$250.00 per package.

FN=Factory New/NS=New Surplus/OH=Overhaul Certified/SV=Serviceable/RP=Repaired/AR=As Removed

Continued on next page...



PRIME INDUSTRIES, INC.

406 Dividend Drive

Peachtree City, GA 30269 Tel: (770) 632-1851 UNITED STATES
Fax: (770) 632-1852
www.primeindustriesusa.com



REPAIR & OVERHAUL QUÖTE

Print Date: Apr-25-2024 4:48 PM Printed By: Marc Lacourly Print No.: 2

Our Ref: 123698-ML Fin.Dest.; MALAYSIA Quotation No. 123698 Page: 2/3

Your Ref.; RMN-24-1591

| Line | P/N & Description | Cnd | Qty Bid | Delivery | Unit Price | Amount |
|------|---|---------|----------------------------|-------------------|------------|--------|
| | TURN AROUND TIME (DAYS): 21 | | | | | |
| | | | | | | |
| | | | | | | |
| | APPROVAL SIGNATURE: | DA | ΓΕ: | | | |
| | | | | | | |
| | NAME: | | | | | |
| | | | | | | |
| | | | | | | |
| | *** END-USE INFORMATION *** | | | | | |
| | EXPORTING TO : MALAYSIA | | | | | |
| | APPLICATION :STOCK | | | | | |
| | SCHEDULE B / H.S. # :8807.30.0060 | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | ESTIMATE QUOTES DEPENDING ON CONDITIO | N OF | THE UNITS. | | | |
| | | | | | | |
| | EXPORT COMPLIANCE STATEMENT | | | | | |
| | | | | | | |
| | Products sold by PRIME INDUSTRIES, INC. may require a license from the U.S. Department of State, the U.S. Department of Commerce, or the U.S. Department of Treasury to be exported/shipped | | | | | |
| | · | | | | a a b l a | |
| | out of the United States. PRIME INDUSTRIES, INC United States Export Control Regulations including | | | 1 | cable | |
| | in Arms Regulations (ITAR), the Export Administrati | ſ | • | | | |
| | Assets Control (OFAC), and the Foreign Corrupt Pr | 1 | · · · | | | |
| | of products requiring a license from the U.S. Depart | 1 | | | re | |
| | or products requiring a neerise from the 0.5. Depart | THO THE | or State, the G.S. Departi | TICHE OF COMMINIC | 001 | |

- 1. Prime Industries' Standard Terms & Conditions of Sale apply, see WWW.PRIMEINDUSTRIESUSA.COM.
- 2. Prices & deliveries are quoted in business day and are applicable to the quantities as covered by this quotation.
- 3. All materials quoted from stock or with deliveries of 15 days or less are subject to prior sale.
- 4. In the event of an order, the above commodities are not to be shipped to any country that has an embargo placed against it by the U.S. Government. Should these commodities require an export license, it shall be your responsibility to comply with the United States Department of State/Commerce Export Regulations.
- 5. If an Export License is required, a \$250.00 processing fee will apply for each occurrence
- 6. Hazardous Material (HAZMAT) Shipments shall be subject to a minimum Haz-Mat handling fee of \$250.00 per package.

FN=Factory New/NS=New Surplus/OH=Overhaul Certified/SV=Serviceable/RP=Repaired/AR=As Removed

Continued on next page...



Line

PRIME INDUSTRIES, INC.

406 Dividend Drive

Peachtree City, GA 30269 Tel: (770) 632-1851

Cnd

UNITED STATES
Fax: (770) 632-1852

www.primeindustriesusa.com

Delivery



Amount

Unit Price

REPAIR & OVERHAUL QUÖTE

P/N & Description

Qty Bid

| | 1714 & Description | Ond | Qty Dia | Delivery | OTIL T TICC | Amount | | |
|-------------|--|---------|---------------------------|---------------|--------------|-------------------|--|--|
| | and/or the U.S. Department of Treasury is strictly pr | ohibite | d. Additionally, PRIME II | NDUSTRIES, IN | C. | | | |
| | correspondence may contain technical data that is | | | | | | | |
| | Traffic in Arms Regulations (ITAR) and/or the Expo | | | | | | | |
| | proper approval from the U.S. Department of State or the U.S. Department of Commerce, the transfer | | | | | | | |
| | or release of this technical data to a foreign person or entity whether manufactured within the | | | | | | | |
| | United States or abroad, is strictly prohibited. | | | | | | | |
| | | | | | | | | |
| | THANK YOU FOR YOUR ORDER | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Sub Total: | \$ 2,335.00 | | | | |
| 1. Prime I | ndustries' Standard Terms & Conditions of Sale apply, see WWW | .PRIME! | INDUSTRIESUSA.COM. | | | | | |
| | & deliveries are quoted in business day and are applicable to the | | | | | | | |
| | erials quoted from stock or with deliveries of 15 days or less are si event of an order, the above commodities are not to be shipped to | | | | | | | |
| | against it by the U.S. Government. Should these commodities req | | | | | | | |
| | sponsibilty to comply with the United States Department of State/Coort License is required, a \$250.00 processing fee will apply for e | | | | | | | |
| 6. Hazard | bus Material (HAZMAT) Shipments shall be subject to a minimum Haz-Mat handling fee of \$250.00 per package. | | | | | | | |
| FN=Facto | ory New/NS=New Surplus/OH=Overhaul Certified/SV=Serviceable | | | | | | | |
| | | | | | Total: [USD] | \$ 2,335.00 | | |
| | | | | | | , , , , , , , , , | | |
| | t (c) PENTAGON <i>2000</i> Software, Inc. 121323] Ver 2021.01.01 Build 5 | | | | | | | |
| JUL #.12000 | 1.2 [323] VEL ZUZ [.U LU L DUHU 3 | | | | | | | |