



# PRIME INDUSTRIES, INC.

406 Dividend Drive  
 Peachtree City, GA 30269 UNITED STATES  
 Tel: (770) 632-1851 Fax: (770) 632-1852  
[www.primeindustriesusa.com](http://www.primeindustriesusa.com)

FEIN 65-1020927



## QUOTATION

Print Date : Jan-06-2021 4:44 PM Printed By : Marc Lacourly Print No. : 2

**For : Account No. [GALAXY]** **No. 112802** Pg:1/2

GALAXY AEROSPACE (M) SDN BHD  
 Attn: Nor Azman Huzir, Support & Logistics Manager  
 SUITE 11-14, HELICOPTER CENTER  
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE  
 SULTAN ABDUL AZIZ SHAH AIRPORT  
 SELANGOR, SUBANG 47200  
 MALAYSIA  
 Tel. : 011 603 7887 0426  
 Fax : 011 603 7887 0526

Our Ref : 112802-ML  
 Terms : WIRE TRANSFER  
 Our Contact : Marc Lacourly  
 eMail : [mlacourly@primeindustriesusa.com](mailto:mlacourly@primeindustriesusa.com)  
 Valid Until : Feb-05-2021  
 F.O.B. : EX-WORKS  
 Quote Date : Jan-06-2021

In response to your request, we are pleased to quote you the following:

| Line | P/N & Description  | Cnd | Qty Bid | Delivery | Unit Price         | Amount       |
|------|--|-----|---------|----------|--------------------|--------------|
| 1    | 355A11-0030-00<br>MAIN ROTOR BLADE<br>Tag Info: FRESH 2021 TCCA/EASA<br>MFG: (F0210) AIRBUS HELICOPTERS<br>Note: TSN 3271.5                          | SV  | 1 EA    | 7 Days   | \$ 45,000.00000 EA | \$ 45,000.00 |
| 2    | 355A11-0030-02<br>MAIN ROTOR BLADE<br>Tag Info: FRESH 2021 TCCA/EASA<br>MFG: (F0210) AIRBUS HELICOPTERS<br>Note: TSN 3296.3                          | SV  | 1 EA    | 7 Days   | \$ 45,000.00000 EA | \$ 45,000.00 |
| 3    | 355A11-0030-04<br>MAIN ROTOR BLADE<br>Trace To: LOG CARDS<br>Tag Info: FRESH 2021 TCCA/EASA<br>MFG: (F0210) AIRBUS HELICOPTERS<br>Note: TSN 11,732.6 | SV  | 1 EA    | 7 Days   | \$ 41,000.00000 EA | \$ 41,000.00 |
| 4    | 355A12-0050-12<br>TAIL ROTOR BLADE<br>Trace To: LOG CARDS<br>Tag Info: FRESH 2021 TCCA/EASA<br>MFG: (F0210) AIRBUS HELICOPTERS<br>Note: TSN 2,022.2  | SV  | 1 EA    | 7 Days   | \$ 23,500.00000 EA | \$ 23,500.00 |
| 5    | 355A12-0041-14   | SV  | 1 EA    | 7 Days   | \$ 35,000.00000 EA | \$ 35,000.00 |

1. Prime Industries' Standard Terms & Conditions of Sale apply. Delivery is quoted in Business Days only,  
 2. Prices & deliveries herein quoted are applicable to the quantities as covered by this quotation.  
 3. All materials quoted from stock or with deliveries of 15 days or less are subject to prior sale.  
 4. In the event of an order, the above commodities are not to be shipped to any country that has an embargo placed against it by the U.S. Government. Should these commodities require an export license, it shall be your responsibility to comply with the United States Department of State/Commerce Export Regulations.  
 5. If an Export License is required, a \$250.00 processing fee will apply for each occurrence  
 6. Hazardous Material (HAZMAT) Shipments shall be subject to a minimum Haz-Mat handling fee of \$250.00 per package.  
 FN=Factory New/NS=New Surplus/OH=Overhaul Certified/SV=Serviceable/RP=Repaired/AR=As Removed

Continued on next page...



# PRIME INDUSTRIES, INC.

406 Dividend Drive  
 Peachtree City, GA 30269 UNITED STATES  
 Tel: (770) 632-1851 Fax: (770) 632-1852  
[www.primeindustriesusa.com](http://www.primeindustriesusa.com)

FEIN 65-1020927



## QUOTATION



Print Date : Jan-06-2021 4:44 PM Printed By : Marc Lacourly Print No. : 2  
 Our Ref : 112802-ML Quotation No. 112802 Page:2/2

| Line | P/N & Description  | Cnd | Qty Bid | Delivery | Unit Price | Amount |
|------|--|-----|---------|----------|------------|--------|
|      | TAIL ROTOR BLADE, NEW PITCH HORN<br>Serial No.: 21954<br>Trace To: LOG CARDS<br>Tag Info: FRESH 2021 TCCA/EASA<br>MFG: (F0210) AIRBUS HELICOPTERS<br>Note: TSN 1525.3<br><br>EXPORT COMPLIANCE STATEMENT<br><br>Products sold by PRIME INDUSTRIES, INC. may require a license from the U.S. Department of State, the U.S. Department of Commerce, or the U.S. Department of Treasury to be exported/shipped out of the United States. PRIME INDUSTRIES, INC. is committed to strict compliance with all applicable United States Export Control Regulations including (but not limited to) the International Traffic in Arms Regulations (ITAR), the Export Administration Regulations (EAR), Office of Foreign Assets Control (OFAC), and the Foreign Corrupt Practices Act (FCPA). The export and re-export of products requiring a license from the U.S. Department of State, the U.S. Department of Commerce, and/or the U.S. Department of Treasury is strictly prohibited. Additionally, PRIME INDUSTRIES, INC. correspondence may contain technical data that is controlled and compliant with the International Traffic in Arms Regulations (ITAR) and/or the Export Administration Regulations (EAR). Without the proper approval from the U.S. Department of State or the U.S. Department of Commerce, the transfer or release of this technical data to a foreign person or entity whether manufactured within the United States or abroad, is strictly prohibited.<br><br>THANK YOU FOR YOUR ORDER |     |         |          |            |        |

Sub Total: \$ 189,500.00

1. Prime Industries' Standard Terms & Conditions of Sale apply. Delivery is quoted in Business Days only,
  2. Prices & deliveries herein quoted are applicable to the quantities as covered by this quotation.
  3. All materials quoted from stock or with deliveries of 15 days or less are subject to prior sale.
  4. In the event of an order, the above commodities are not to be shipped to any country that has an embargo placed against it by the U.S. Government. Should these commodities require an export license, it shall be your responsibility to comply with the United States Department of State/Commerce Export Regulations.
  5. If an Export License is required, a \$250.00 processing fee will apply for each occurrence
  6. Hazardous Material (HAZMAT) Shipments shall be subject to a minimum Haz-Mat handling fee of \$250.00 per package.
- FN=Factory New/NS=New Surplus/OH=Overhaul Certified/SV=Serviceable/RP=Repaired/AR=As Removed

  
 Marc Lacourly, President

Total: [USD] \$ 189,500.00