

QUOTATION

G7 AEROSPACE SDN BHD

523830-H A-2-01 CoPlace 1 2270 Jalan Usahawan 2 63000 Cyberjaya, Selangor Malaysia

Phone (603) 8322 6393 Fax (603) 8322 6693

To:

GALAXY AEROSPACE (m) SDN BHD Suite 11-14, Helicopter Center, Malaysia International Aerospace Center Sultan Abdul Aziz Shah Airport, 47200 SUBANG Selangor Date: 14/08/2023

Quotation No: G7/QTN/038-23

Prepared by: Mohd Sani

REPAIR QUOTATION

Item: ECS Fan Blower

Part Number: WG 1474-0018-001

Serial Number: 494007

REPORT:

Owner of Defective Item: Galaxy Aerospace

Initial Defect: Blower Fan defective

Visual inspection and initial functional test carried out found:

- Visual and physical check carried out, found item in good physical condition and have no crack.
- External housing is contaminated with dirt.
- Visual and physical check carried out, found item in good physical condition and have no crack.

Fan assembly was disassembled so that component per component troubleshooting and fault isolation detection was carried out and the following were found:

- Blade is still in a good condition but has contaminated with dirt.
- Motor is still in a good condition.
- Bearings were removed, inspected and found both top and bottom bearing have become defective, the movement is not smooth. Bearings require replacement.

Rectification Plan:

- a. Defective bearings need to be replaced
- b. Testing to be carried out after repaired.
- c. Clean all parts from dirt and rust.
- d. Reassemble all components after inspected, checked, and cleaned.
- e. Perform a loose article check on all components to ensure they are all accounted for.
- f. To carry out functional test within a set duration of time to ensure functionality after repair
- g. Quality checks to ensure check and balance of items.

SERVICE COST:

No.	DESCRIPTION	AMOUNT (RM)
1.	Receipt, Tear Down Inspection and Testing	2,700.00
2.	Repair Services	2,400.00
3.	Reassembly	900.00
4.	Pre-test & Final Testing	750.00
5.	Spare Part	750.00
	SUBTOTAL	7,500.00
	TOTAL	7,500.00

SPARE PART

NO	DESCRIPTION	QUANTITY	UNIT PRICE	TOTAL
1	Bearings	02	375.00	750.00
	750.00			

Notes:

- 1) The quotation is valid for 30 days from quotation issuance.
- 2) Prices are based on effective price list at the date of quotation and maybe subject to variation.
- 3) Lead Time: 30 Days from receipt of quotation acceptance.
- 4) Payment Terms: 30 days after invoice issued.
- 5) G7 Aerospace Bank Details:

Bank Name : CIMB Bank Berhad

Bank Address : Prima 5-A, Jalan Teknokrat 5, 63000 Cyberjaya, Selangor, Malaysia

Account Name : G7 Aerospace Sdn Bhd

Account Number : 8003225779
Bank Swift Code : CIBBMYKL

Please contact us should you have any questions concerning this quotation, contact name, phone number.

For and on behalf, **G7 Aerospace Sdn Bhd**

Mohd Sani bin Muhamad Yunos

Operations Manager

THANK YOU FOR YOUR BUSINESS!