









-  **Inbox** 3
-  Starred
-  Snoozed
-  Sent
-  Drafts
-  9M-PM



Meet

-  New meeting
-  Join a meeting

Hangouts

- N
Nor Izzati ▾
+




No recent chats
[Start a new one](#)

RE: [External] RFQ [Repair] ; DCU-DATA COLLECTION UNIT(PN:3059179-02)  

CRM:00145000195 Inbox x



GP PWC PWCS NOZZLES
to izzatiazmi@galaxyaerospace.my, Ivan, store@galaxyaerospace.my ▾

May 21, 2021, 4:18 AM (3 days ago)   

Hello,

The average repair price for PN: 3059179-02 starts at \$2,034.27, however the cost of your repair is dependent upon the condition of your individual unit and is subject to additional extended repair costs. You will be provided a repair disposition with quote upon our receipt from the vendor and the part will be released into work upon your acceptance of the charges.

The turnaround time this repair is typically 27 days, this time period begins the day we receive all required information to process the order. If you wish to have us manage your repair, please ship the unit to the address below. Please be sure to include a copy of your repair order. Also note, engine serial numbers are required for all repairs.

P&WC Parts Distribution Center
Attn: Repairs
P&W Component Solutions, Inc.
7010 Grand Haven Rd. Suite 300
Norton Shores, MI 49456

- 
- 
- 
- 