

Quote

Your Ref No : -
Date : 24-Nov-22
Customer ID : SMGA

To: Galaxy Aerospace (M) Sdn Bhd
Suite 11-14, Helicopter Centre
Malaysia International Aerospace Centre
Sultan Abdul Aziz Shah Airport
47200 Subang, Selangor
Attn :

Aircraft : M 72-01 (AW 139)

S/N	Description	Subject	Total Package (RM)	
1	Left angle frame support for fuel tank area found crack at the edges (STA 5795.0, BL-550.0) fuel tank upper support frame area	To replace new external doubler, anchor nut & primer		
2	Right angle frame support for fuel tank area found crack at the edges (STA 5795.0, BL+550.0) fuel tank upper support frame area	To replace new external doubler, anchor nut & primer		
			RM	18,000.00
3	Right angle forward frame support for fuel tank area found crack at the edges (STA 5795.0, WL+2470.0) fuel tank upper support frame area	Replace new external STEEL doubler, anchor nut & primer		
4	Left angle forward frame support for fuel tank area found crack at the edges (STA 5795.0, WL-2470.0) fuel tank upper support frame area	Replace new external STEEL doubler, anchor nut & primer		
Manpower : 04 TAT : 8 days Aircraft Type : M 72-01 (AW 139)			Subtotal	RM 18,000.00
			Sales Tax	
			Total	RM 18,000.00

Prepared by
(Fiza Abu Bakar)
SMASSB



"To Serve You Better"