



406 Dividend Drive  
 Peachtree City, Georgia 30269  
 Phone (770) 632-1851  
 Fax: (770) 632-1852

# Repair Estimate

|                             |                              |  |
|-----------------------------|------------------------------|--|
| <b>LOG CARD:</b>            | YES <input type="checkbox"/> | NO <input checked="" type="checkbox"/> |
| <b>SPECIAL INSTRUCTION:</b> | <input type="checkbox"/>     | <input checked="" type="checkbox"/>    |
| <b>UNIT MISUSED:</b>        | <input type="checkbox"/>     | <input checked="" type="checkbox"/>    |
| <b>PICTURES:</b>            | <input type="checkbox"/>     | <input checked="" type="checkbox"/>    |

|                            |              |
|----------------------------|--------------|
| <b>DATE:</b>               | 9-May-2022   |
| <b>PRIME REFERENCE:</b>    | 51092        |
| <b>CUSTOMER REFERENCE:</b> | RMN-22-285   |
| <b>PART NUMBER:</b>        | 597-2247-001 |
| <b>SERIAL NUMBER:</b>      | 1180         |
| <b>DESCRIPTION:</b>        | EDU-4085F    |
| <b>WORK REQUESTED:</b>     | REPAIR       |

**EVALUATIONS / FINDINGS:**  
 SMELL BURNT UP DUE TO BURNED COMPONENTS ON VIDEO CARD. THE VIDEO CARD IS NO REPAIRABLE BECAUSE SEVERAL TRACKS ARE BURNT ON CIRCUIT CARD. ALSO FOUND DEFECTIVE DEFLECTION CARD.

**CORRECTIVE ACTIONS TO BE CARRIED OUT:**  
 UNIT REQUIRES REPAIR

**PARTS REPLACED OR REPAIRED**

EXCLUSIONS:       **CONDITION AFTER COMPLETION:**

| PART NUMBER | DESCRIPTION | STATUS | QUANTITY | PRICE |
|-------------|-------------|--------|----------|-------|
|             |             |        |          |       |
|             |             |        |          |       |
|             |             |        |          |       |

**FLAT RATE:**

**TOTAL QUOTE**

**TOTAL QUOTE OPTION #1**

**TURN AROUND TIME AFTER APPROVAL: (IN BUSINESS DAYS)**

**EVALUATION FEE IF QUOTE DENIED**

**COMMENTS:**

Approval Signature: \_\_\_\_\_

Name: \_\_\_\_\_ Date: \_\_\_\_\_