



406 Dividend Drive
 Peachtree City, Georgia 30269
 Phone (770) 632-1851
 Fax: (770) 632-1852

Repair Estimate

LOG CARD:	YES <input type="checkbox"/>	NO <input checked="" type="checkbox"/>
SPECIAL INSTRUCTION:	<input type="checkbox"/>	<input checked="" type="checkbox"/>
UNIT MISUSED:	<input type="checkbox"/>	<input checked="" type="checkbox"/>
PICTURES:	<input type="checkbox"/>	<input checked="" type="checkbox"/>

DATE:	11-May-2022
PRIME REFERENCE:	051191
CUSTOMER REFERENCE:	RMN-22-309
PART NUMBER:	4679078A
SERIAL NUMBER:	0853
DESCRIPTION:	RADIO ALTIMETER
WORK REQUESTED:	REPAIR

EVALUATIONS / FINDINGS:
OPTICAL ENCODER AND ROTACTOR NEEDS REPLACED
LCD MODULE FOUND BAD AND NEEDS REPLACED

CORRECTIVE ACTIONS TO BE CARRIED OUT:
UNIT REQUIRES REPAIR

PARTS REPLACED OR REPAIRED

EXCLUSIONS:	NO	CONDITION AFTER COMPLETION:	REPAIRED
--------------------	----	------------------------------------	----------

PART NUMBER	DESCRIPTION	STATUS	QUANTITY	PRICE

FLAT RATE:	<input type="text"/>	COMMENTS: LCD MODULE NEEDS REPLACED
TOTAL QUOTE	\$8,795.00	
TOTAL QUOTE OPTION #1	<input type="text"/>	
TURN AROUND TIME AFTER APPROVAL: (IN BUSINESS DAYS)	60 DAYS	Approval Signature: _____
EVALUATION FEE IF QUOTE DENIED	<input type="text"/>	Name: _____ Date: _____