SAFRAN AEROSYSTEMS SERVICES ASIA SHOP FINDIN		
SAFRAN OVERHAULED		
CUSTOMER: GALAXY AEROSPACE (M) SDN BHD	ORDER No: 1159718 / 0051181808	
CUSTOMER ORDER: MMA-24-1090	RECEIVED DATE: 08-08-24 (DD-MM-YY)	
CUSTOMER INSTRUCTION: EASA FORM 1 / FAA 8130-	-	
RECEIVING		
DESCRIPTION: L/H AFT FLOTATION ASSY	REF AIRCRAFT MANUFACTURER: 158950-4	
RECEIVED PART NUMBER: 158950-4	MANUFACTURER:	
	ARZ141 SAFRAN AEROSYSTEMS COGNAC DSE	
SERIAL NUMBER: N/A	CAGE CODE: F6101	
AMENDMENT: N/A	MANUFACTURING DATE: 01-10-19 (DD-MM-YY)	
QUANTITY: 1	REMOVAL DATE: 09-05-24 (DD-MM-YY)	
LAST OHL DATE NIL TSN:	TSO: TSR:	
	ס. <u>ג/מ</u> וד דערסע האייני.	

AIRCRAFI:	REGISTRATION NUMBER:	A/C DELIVERI DALE:
AS365N3	UNKNOWN	UNKNOWN
Maintenance Documentation Re Amendment: N/A Documentation: CMM 25-69-21 Rev Work Performed: See Attached Re SB/SIL Performed: SIL 025-69-07 AD Compliance: N/A Including Balloon P/N: 159128-2 60 months major inspection <u>Reason for Removal</u> REMOVED DUE FOR 1Y AND 5Y INSP <u>Findings</u> Received flotation assy in pack	v.17 epair Report: 1159718 7 Rev.04 2, S/N: 3358 (DOM: 10-2019) ked condition.	
60 months major inspection to I	be carried out.	
All others sub-components in acceptable condition.		
<u>Work to be performed &amp; parts to</u> Overhauled, 60 month major insp test and folding.	<u>o be replaces/Travaux à réaliser &amp; p</u> pection with proof test, leak	ièces à remplacer
Replacement of part: O-ring (O and Plastic rivet (Oty: 14). <u>Remarks</u>	ty: 02), Lead seal (Qty: 02)	
Log card received with float as	SSY.	
Customer liability Yes		
	SHIPPING	
SHIPPED PART NUMBER: 1589	50-4 REF AIRC	RAFT MANUFACTURER: 158950-4
SERIAL NUMBER: N/A		
AMENDMENT : N/A		
DATE: 12-08-24 (DD-MM-YY)	WRITER: Ooi Jun Siang	INSPECTOR:

Signature

Signature