

CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

TO: All Engineering Department, CAMO and Design/Technical Services Department	FROM: Technical Publication
CC: GAM QA Department, GAM AM	DATE: 19.03.2021
REFERENCE NO.: CAMO/MEMO/2021/08	

Dear all,

Please be informed that the following publication has been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement.

NO.	VENDOR	REF. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1	P&WC	REV. 26	08.03.2021	PT6C-67C	ENGINE MAINTENANCE MANUAL DOC. REF.: 3045332	1
2	P&WC	REV. 69	01.03.2021	PT6A-60A	PARTS CATALOGUE DOC. REF.: 3034344	2
3	AIRBUS	REV. 007	22.01.2021	EC155B	AIRWORTHINESS LIMITATION SECTION (ALS) CHAPTER 04	3
4	AIRBUS	REV. 010	22.01.2021	EC155B	MASTER SERVICING MANUAL (MSM) CHAPTER 05	4
5	LEONARDO	ISE NO. 109E-008 NEW ISSUE	26.02.2021	A109E	INSPECTION OF ROTOR BRAKE CONTROL CABLE P/N 109-0506-17- 113	5
6	LEONARDO	ISE NO. 109-007 NEW ISSUE	25.02.2021	A109E	ONE TIME INSPECTION OF TAIL ROTOR SHAFT ASSY P/N 109-0445- 08-7/-113/-117	6
7	HARTZELL	REV. 18	01.03.2021	HC-B4MP-3C	PROPELLER OWNER'S MANUAL AND LOGBOOK DOC. REF.: MANUAL NO. 139 (61- 00-39)	7
8	GENERAL ELECTRIC	IC 72-00-00- 100-E-001 GEK112043- 02, REV. 3	04.03.2021	CT7-2E1	INCREMENTAL CHANGES - FADEC FAULT ISOLATION	8
9	GENERAL ELECTRIC	IC 73-00-00- 400-E GEK112043- 02, REV. 3	04.03.2021	CT7-2E1	INCREMENTAL CHANGES - FUEL SYSTEM - REMOVAL AND INSTALLATION	9
10	GENERAL ELECTRIC	IC 72-36-00- 400-E GEK112043- 02, REV. 3	04.03.2021	CT7-2E1	INCREMENTAL CHANGES - COMPRESSOR STATOR ASSEMBLY - REMOVAL AND INSTALLATION	10

11	GENERAL ELECTRIC	TR 05-0015 GEK112043-02, REV. 3	04.03.2021	CT7-2E1	TEMPORARY REVISION - TIME LIMITED DISPATCH 001 CONTROL SYSTEM - TIME LIMITED DISPATCH	11
12	GENERAL ELECTRIC	IC 72-00-00-500-E GEK112043-02, REV. 3	04.03.2021	CT7-2E1	INCREMENTAL CHANGES – ENGINE - TEST	12
13	LEONARDO	REV. D	03.03.2021	AW189	MASTER MINIMUM EQUIPMENT LIST DOC. REF.: 189G0270Q001	13
14	AIRBUS	IN NO. 3634-I-00, REV. 0	04.03.2021	EC120B, EC155B & AS365	DRY ICE TRANSPORTATION (SOLID CO2)	14
15	AIRBUS	SIN NO. 3638-S-63 REV. 0	12.03.2021	EC120B	MAIN ROTOR DRIVE - REMINDER ON THE IMPORTANCE OF COLLECTING, CHARACTERIZING AND FOLLOWING UP PARTICLES IN DYNAMIC COMPONENT LUBRICATION SYSTEMS	15
16	P&WC	SIL NO. PW200-078 REV. 3	09.03.2021	PW206C & PW207D1	SERVICE INFORMATION LETTER ADDITIONAL SB28387 COMPLIANCE CODE 3 AND NEW SCHEDULED MAINTENANCE OF OIL FILTER	16
17	AIRBUS	REV. 007	22.02.2021	EC155	O.R.I.O.N. SOFTWARE (Offline)	17


Kindly reminder to all,

Item no. 1 and 2: You may patch the WINZIP file into your own Pratt and Whitney Canada ETP software.

Item no. 17: You may remove the older revision and patch the whole folder of ORION into My Computer or C: folder to avoid any lagging system.

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

Thank you and stay safe!



NUR NABILLA BT. MOHD HASNAN
TECHNICAL PUBLICATION,
CAMO DEPARTMENT,
GALAXY AEROSPACE (M) SDN. BHD.