

CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

TO: ALL ENGINEERING & CAMO DEPARTMENT	FROM: CAMM
CC: QUALITY ASSURANCE DEPARTMENT	DATE: 30 DECEMBER 2019
REFERENCE NO.: CAMO/MEMO/2019/46	

Dear all,

Please be informed that the following publication has been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement.

NO.	VENDOR	REF. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1.	PRATT AND WHITNEY CANADA	REVISION 23.2	10.12.2019	PT6C ENGNE	PT6C ENGINE MAINTENANCE MANUAL - THIS REVISION REVISE TO INCLUDE 3 NEW TEMPORARY REVISION: <ul style="list-style-type: none"> TEMPORARY REVISION 05-21 (SCHEDULED MAINTENANCE CHECKS) TEMPORARY REVISION 72-14 (ENGINE - INSPECTION) TEMPORARY REVISION 72-15 (COMPRESSOR ROTOR - MAINTENANCE PRACTICES) 	<u>1</u>
2.	PRATT AND WHITNEY CANADA	REVISION 18	02.12.2019	ALL PW207	NEW UPDATE ON PW207 ILLUSTRATED PARTS CATALOGUE	<u>2</u>
3.	LEONARDO	ISE 139-014 NEW ISSUE	11.12.2019	AW139	AW139 EMERGENCY FLOTATION SYSTEM SUPPLY HOSE INSPECTION	<u>3</u>
4.	LEONARDO	TMI 139-393 REVISION A	05.12.2019	AW139	RIGHT BRACKET ASSY – REPLACEMENT	<u>4</u>

NO.	VENDOR	REF. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
					PROCEDURE (REMOVE AND INSTALL A NEW ITEM)	
5.	LEONARDO	TMI 139-513 NEW ISSUE	09.12.2019	AW139	REPLACEMENT OF REINFORCEMENT BRACKET P/N 3P5338A14351 (L/H) or 3P5338A14451 (R/H) at STA 6700, BL 950, WL 830	5
6.	LEONARDO	TMI 139-515 NEW ISSUE	03.12.2019	AW139	SPAR BUSHINGS (MAIN ROTOR BLADE) – REPLACEMENT	6
7.	PRATT AND WHITNEY CANADA	SIL NO PT6C-037 NEW ISSUE	10.12.2019	PT6C-67C	RECURRING INSPECTIONS OF THE POWER TURBINE (PT) BAFFLE RETAINING RING	7
8.	AIRBUS HELICOPTER	IN 3432-I-00 NEW ISSUE	10.12.2019	ALL EC155	TECHNICAL PUBLICATIONS: UPCOMING REVISION OF THE H155/EC155 PUBLICATIONS (CHAPTER 4 (ALS) & CHAPTER 5 (MSM))	8
9.	AIRBUS HELICOPTER	REVISION 006	25.11.2019	ALL EC155	EC155B e-TECHNICAL PUBLICATION UPDATE MAINTENANCE DOCUMENT: O.R.I.O.N. EC155 VERSION 2.1	9
10.	LEONARDO	TMI 139-510 REVISION A	12.12.2019	AW139	UNDRESSING PROCEDURE – POWER SUPPLY P/N 071-01041-0001	10
11.	LEONARDO	TMI 139-517 NEW ISSUE	11.12.2019	AW139	MULTI-PURPOSE FLIGHT RECORDER – RETURN TO BASIC AND BUILD UP TO USABLE CONFIGURATION	11
12.	LEONARDO	TMI 139-518 NEW ISSUE	12.11.2019	AW139	MAST-PLANETARY ASSEMBLY (UPPER MODULE) – ASSEMBLE PROCEDURE	12
13.	LEONARDO	ISE 139-015 NEW ISSUE	18.12.2019	AW139	UPDATE ON AW139 MGB BEARING LOCK-NUT REPLACEMENT	13
14.	GOODRICH	SIL-2018-05, REVISION 1	21.10.2019	AW139 & AW189	EQUIPMENT/FURNISHINGS – RESCUE HOIST – GEARBOX SERVICING	14

NO.	VENDOR	REF. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
15.	LEONARDO	ISE NO 189-013 NEW ISSUE	19.12.2019	AW189	FIRE EXTINGUISHER REPLACEMENT	15
16.	PRATT AND WHITNEY CANADA	S.I.L NO. GEN-122 REV. 8	20.12.2019	ALL MODEL OF P&WC ENGINE	RECOVERY FEE FOR MAINTENANCE DEVIATION LETTERS	16
17.	AIRBUS HELICOPTER	SIN NO 3444-S-25 REVISION 0	20.12.2019	ALL TYPE OF AIRBUS HELICOPTERS	EQUIPMENT AND FURNISHINGS - CORRECT USE OF SEATS AND RESTRAINT SYSTEMS TO MINIMIZE THE RISK OF INJURY	17
18.	LEONARDO	REVISION U	23.12.2019	AW139	NEW REVISION ON COMPATIBILITY REFERENCE HANDBOOK (CRH-NVG)	18
19.	LEONARDO	ISSUE 24	13.11.2019	AW139	AW139 COMPONENT MAINTENANCE PUBLICATION (CMP)	19
20.	LEONARDO	PRATT AND WHITNEY CANADA	02.12.2019	PW206C	NEW REVISION ON PW206C ILLUSTRATED PARTS CATALOGUE	20

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

Thank You.



ZATY NADHIRA BINTI MOHAMED ZUHARI
CONTINUING AIRWORTHINESS MANAGEMENT MANAGER
GALAXY AEROSPACE (M) SDN. BHD.