

CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

TO: ALL ENGINEERING & CAMO DEPARTMENT	FROM: CAMM
CC: QUALITY ASSURANCE DEPARTMENT	DATE: 06 FEBRUARY 2020
REFERENCE NO.: CAMO/MEMO/2020/05	


Dear all,
Please be informed that the following publication has been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement.

NO.	VENDOR	REF. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1	LEONARDO	ISSUE 1, REV. 7	17.12.2019	AW139	NEW REVISION ON MMEL (EASA)	<u>1</u>
2	PRATT AND WHITNEY CANADA	SIL NO PT6C-034 REV. 1	27.01.2020	PT6C ENGINES	P&WC TURBOSHAFT CUSTOMER DAY 2020	<u>2</u>
3	SAFRAN	SIL NO 342-SL-07 REV. 002	11.12.2019	e-APU 60	e-APU 60 MODEL 342 – APU POWER CHECK	<u>3</u>
4	SAFRAN	SIL NO 342-SL-04 REV. 002	11.12.2019	e-APU 60	e-APU 60 MODEL 342 – GENERAL WARRANTY CONDITIONS	<u>4</u>
5	LEONARDO	ISSUE 18 TH UPDATE 003	23.01.2020	AW189	NEW UPDATE ON AW189 IETP	<u>5</u>
6	LEONARDO	ISE 189-014 NEW ISSUE	31.01.2020	AW189	AW189 TAIL ROTOR ACTUATOR IMPROVEMENT	<u>6</u>
7	LEONARDO	DOC. NO. 189G0000A002 ISSUE O	28.01.2020	AW189	AW189 KIT COMPATIBILITY REFERENCE HANDBOOK	<u>7</u>
8	LEONARDO	IL AW189-20-003 NEW ISSUE	05.02.2020	AW189	STARTER GENERATOR IMPROVEMENT	<u>8</u>
9	LEONARDO	TMI 109-464 REVISION B	28.01.2020	ALL TYPE A109 AND A119	MAIN ROTOR BLADE ASSY – REPLACEMENT OF THE TRIM TAB	<u>9</u>
10	SAFRAN	REF. VERSION: 008175-3 (U015)	16.09.2019	ARRIEL 2C1	ARRIEL 2C1 QUALITY DOCUMENTS – INSTRUCTIONS FOR PREPARING AND UPDATING COMPONENT LOG CARDS	<u>10</u>

NO.	VENDOR	REF. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
11	AIRBUS	IN 3140-1-00 REV. 3	21.01.2020	EC155B, EC155B1	IMPROVEMENT OF THE HANDLING AND LOGISTICS OF SELECTED DYNAMIC COMPONENTS	11
12	SAFRAN	WINTER 2019-2020	31.01.2020	ARRIEL 2C	ARRIEL 2C PROGRESS REPORT	12
13	AIRBUS	IN 3447-I-00 REV. 0	24.01.2020	EC155B/B1 & EC120B	INTRODUCTION OF THE DIGITAL SERVICE BULLETIN REPORTING SERVICE R-TEX	13
14	AIRBUS	SPN 3399-P-20 REV. 0	24.01.2020	EC155B/B1 & EC120B	STANDARD PRACTICES - RECOMMENDATIONS FOR VISUAL INSPECTIONS - HUMAN FACTOR APPROACH	14
15	AIRBUS	SIN 3463-S-00 REV. 0	04.02.2020	EC155B/B1 & EC120B	GENERAL – VOTEX RING STATE/AIRBUS HELICOPTER TRAINING RECOMMENDATIONS AND CONSIDERATIONS ABOUT THE “VUICHARD RECOVERY TECHNIQUE”	15
16	PRATT AND WHITNEY CANADA	PART NO.: 3043322 REV. 38.0	09.12.2019	PW206C	PW206C MAINTENANCE MANUAL (ETP VERSION)	16
17	PRATT AND WHITNEY CANADA	SIL PW200-078 NEW ISSUE	04.02.2020	PW200 SERIES	RECOMMENDED OIL FILTER ANALYSIS AS MITIGATION TOOL FOR PRE SB28387 ENGINES	17
18	BHTC	BHT-429-IPB REV. 19	30.05.2019	429	NEW UPDATE ON 429 ILLUSTRATED PART BREAKDOWN MANUAL	18

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

Thank You.



ZATY NADHIRA BINTI MOHAMED ZUHARI
CONTINUING AIRWORTHINESS MANAGEMENT MANAGER
GALAXY AEROSPACE (M) SDN. BHD.