

## CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

<b>TO:</b> ALL ENGINEERING & CAMO DEPARTMENT	<b>FROM:</b> TECHNICAL PUBLICATION
<b>CC:</b> QUALITY ASSURANCE DEPARTMENT	<b>DATE:</b> 08 MAY 2020
<b>REFERENCE NO.:</b> CAMO/MEMO/2020/24	

Dear all,

Please be informed that the following publication has been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement.

NO.	VENDOR	REF. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1	PRATT AND WHITNEY CANADA	S.I.L NO. GEN-153R4 NEW ISSUE	05.05.2020	ALL P&WC ENGINE MODELS	OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION	<a href="#">1</a>
2	BHTC	IL GEN-20-147 NEW ISSUE	05.05.2020	ALL BELL PRODUCT'S OWNER AND OPERATOR	BELL SPARES SYSTEM PART NUMBER SUBSTITUTION	<a href="#">2</a>
3	LEONARDO HELICOPTER	TMI 139-407 REV. B	29.04.2020	AW139	LEFT/RIGHT PROFILE P/N 3P5340A13751/ -851 REPLACEMENT	<a href="#">3</a>
4	LEONARDO HELICOPTER	TMI 139-417 REV. D	30.04.2020	AW139	REAR FUSELAGE RH CENTRAL FITTING AT STA 8700 P/N 3P5340A14253 – REPLACEMENT PROCEDURE	<a href="#">4</a>
5	LEONARDO HELICOPTER	TMI 139-527 NEW ISSUE	04.05.2020	AW139	ROLE CHANGE PROCEDURE – FIPS PARTIAL REMOVAL	<a href="#">5</a>
6	AIRBUS HELICOPTER	IN NO. 3492-I-25 REV. 4	30.04.2020	EC155/EC120B	EQUIPMENT AND FURNISHINGS - ISOLATION BETWEEN COCKPIT AND PASSENGER COMPARTMENT	<a href="#">6</a>
7	PRATT AND WHITNEY CANADA	REV. 54.2	04.05.2020	PT6A-60A	ENGINE MAINTENANCE MANUAL	<a href="#">7</a>

Kindly reminder to all:

For item no. 7, you need to install the Winzip file (as per attached) and click update in Pratt and Whitney Canada ETP, respectively.

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately. Software can be download from GAM Server.

Thank You.



NUR NABILLA BT. MOHD HASNAN  
**TECHNICAL PUBLICATION**  
**GALAXY AEROSPACE (M) SDN. BHD.**