

CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

TO: ALL ENGINEERING & CAMO DEPARTMENT	FROM: TECHNICAL PUBLICATION
CC: QUALITY ASSURANCE DEPARTMENT	DATE: 04.08.2020
REFERENCE NO.: CAMO/MEMO/2020/27	

Dear all,

Please be informed that the following publication has been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement.

NO.	VENDOR	REF. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1	LEONARDO	ISE 139-017 NEW ISSUE	03.06.2020	AW139	HOIST CABLE CUTTER FRAME INSTALLATION	1
2	PRATT AND WHITNEY CANADA	EMM REV. 25	01.06.2020	PT6C-67C	ENGINE MAINTENANCE MANUAL MANUAL PART NO: 3045332	2
3	LEONARDO	CHAPTER 00 – ISSUE 008 CHAPTER 04 – ISSUE 012 CHAPTER 05 – ISSUE 021	CH. 00 – 05.06.2018 CH. 04 – 01.08.2019 CH. 05 – 10.06.2020	AW139	AIR VEHICLE MAINTENANCE PLANNING INFORMATION (AMPI)	3
4	LEONARDO	TMI 139-530 NEW ISSUE	25.06.2020	AW139	SPONSON - PREPARATION BEFORE INSTALLATION	4
5	LEONARDO	TMI 189-045 NEW ISSUE	19.06.2020	AW189	HEATED WINDSHIELDS INSTALL PROCEDURE	5
6	GENERAL ELECTRIC	MANUAL PART NO.: GEK112043- 02 REV. 3	30.06.2020	CT7-2E1	ENGINE MAINTENANCE MANUAL	6
7	GENERAL ELECTRIC	MANUAL PART NO.: GEK115715 REV. 4	30.06.2020	CT7-2E1	ENGINE ILLUSTRATED PARTS MANUAL	7
8	GENERAL ELECTRIC	MANUAL PART NO.: GEK9250 REV. 109	01.04.2020	CT7-2E1	ENGINE STANDARD PRACTICES MANUAL	8
9	PRATT AND WHITNEY CANADA	MANUAL PART NO.: 3043324 REV. 43.0	01.06.2020	PW206C/ PW207C	PW206C PARTS CATALOGUE	9
10	PRATT AND WHITNEY CANADA	S.I.L NO. PW200- 078 REV. 2	16.06.2020	ALL PW200 ENGINE TYPE	RECOMMENDED OIL FILTER ANALYSIS FOR PRE-SB28387 ENGINES	10
11	AIRBUS	IN NO. 3492-I-25 REV. 5	02.06.2020	EC155/EC120B	ISOLATION BETWEEN COCKPIT AND PASSENGER COMPARTMENT	11

NO.	VENDOR	REF. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
12	AIRBUS	SPN NP. 3528-P-00 REV. 0	05.06.2020	EC155/EC120B	INTERNATIONAL HELICOPTER SAFETY FOUNDATION (IHSF, FORMWELY IHST) SURVEY ON TECHNOLOGIES WITH SAFETY BENEFITS	12
13	AIRBUS	IN NO. 3440-I-34 REV. 1	05.06.2020	EC155	NAVIGATION - NEW SOFTWARE VERSION 241Q FOR FREEFLIGHT GPS 2101 I/O APPROACH +	13
14	AIRBUS	SIN NO. 3529-S-25 REV. 0	24.06.2020	EC155	EQUIPMENTS AND FURNISHINGS - MEASURES TO BE TAKEN IF THE HOIST JAMS IN OPERATION	14
15	SAFRAN	TCB NO. E50_006_20	18.06.2020	ARRIEL 2	TM5563G002 CANCEL AND REPLACE 8813779000 TO BLANK THE MODULE 2 ISOLATED	15
16	AIRBUS	SIN NO. 3529-S-25 REV. 1	30.06.2020	EC155	EQUIPMENT AND FURNISHINGS - MEASURES TO BE TAKEN IF THE HOIST JAMS IN OPERATION	16
17	PRATT AND WHITNEY CANADA	S.I.L NO. PW200-078 REV. 2	16.06.2020	ALL PW200 ENGINE TYPE	RECOMMENDED OIL FILTER ANALYSIS FOR PRE-SB28387 ENGINES	17
18	PRATT AND WHITNEY CANADA	P&WC IPC REV. 19	01.06.2020	PW207D1/D2	PW207D1/D2 ILLUSTRATED PARTS CATALOGUE (IPC)	18
19	TEXTRON AVIATION	ME-TP-0020 NEW ISSUE	06.2020	B300	ATA 25 – AMSAFE CREW SEATS CONNECTOR WEB SLIDE INSERT AIRCRAFT EQUIPPED WITH AMSAFE CREW SEAT BELTS	19
20	LEONARDO	CS&T/2020/GC041	15.06.2020	A119	A119 CUSTOMER NOTIFICATION ACCIDENT INVOLVING AN A119 IN KENYA	20
21	AIRBUS	ISSUE 2 DATE CODE 16-26	18.11.2019	EC120B	EC120B FLIGHT MANUAL	21
22	AIRBUS	O.R.I.O.N. REV. 06	13.04.2020	EC120B	OPTIMIZED READER FOR INTERNET AND OTHER NETWORKS (O.R.I.O.N.)	22
23	CAAM	NOTICE 9/2020 NEW ISSUE	09.06.2020	-	NOTICE ON CAAM OPERATIONS	23
24	CAAM	AG NO. 6106 ISSUE 1	11.06.2020	-	COVID 19 PANDEMIC: AIRWORTHINESS GUIDELINES ON AIRCRAFT CLEANING AND DISINFECTION	24


NO.	VENDOR	REF. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
25	ROCKWELL COLLINS	523-0772076-00711A 7TH EDITION	31.07.1996	APS-85	AUTOPILOT SYSTEM INSTALLATION MANUAL	25
26	PRATT AND WHITNEY CANADA	SIL GEN-160 NEW ISSUE	30.06.2020	ALL P&WC ENGINES	OCCASIONAL DUST PLUME EXPOSURE	26
27	ACCS	PUB NO. 8005013-001 REV. 8	15.06.2020	-	TAWS+ (TERRAIN AWARENESS WARNING SYSTEM) SYSTEM DESCRIPTION AND INSTALLATION MANUAL	27
28	GARMIN	ASDN NO. 2080 REV. A	30.06.2020	-	GARMIN GFC 600 AUTOMATIC FLIGHT CONTROL SYSTEMS OWNERS AND OPERATORS	28

Kindly reminder to all, refer to item no. 2, 9, 18, these Maintenance Manual and Illustrated Parts Catalogue are revisions and need to click on “Flag” icon to update. Please be reminded, you must update the MM and IPC in the Winzip file.

Refer to item no. 6, 7, 22, you need to uninstall the older revision of MM and IPC, then you may install the new revisions.

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately. Software can be download from GAM Server

Thank You.



NUR NABILLA BT. MOHD HASNAN
TECHNICAL PUBLICATION
GALAXY AEROSPACE (M) SDN. BHD.