

## CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

<b>TO:</b> ALL ENGINEERING & CAMO DEPARTMENT	<b>FROM:</b> TECHNICAL PUBLICATION
<b>CC:</b> QUALITY ASSURANCE DEPARTMENT	<b>DATE:</b> 10.08.2020
<b>REFERENCE NO.:</b> CAMO/MEMO/2020/28	

Dear all,

Please be informed that the following publication has been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement.

NO.	VENDOR	REF. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1	BHTC	IL GEN-20-148 NEW ISSUE	06.07.2020	ALL BELL 429	UTILIZATION OF BIOCIDES ADDITIVE IN THE FUEL SYSTEM	<a href="#">1</a>
2	JEPPESEN	MPPA-2007-2008 NEW ISSUE	16.07.2020	ALL JEPPESEN SUBSCRIBERS	JEPPESEN OBSTACLE ALERT - BALBOA PANAMA - PANAMA PACIFICO (MPPA) - CYCLE 2007 & 2008 OBSTACLE MISSING	<a href="#">2</a>
3	PRATT AND WHITNEY CANADA	S.I.L. GEN-158 NEW ISSUE	20.07.2020	ALL P&WC PRODUCTS	HANDLING OF SUSPECTED HEXAVALENT CHROMIUM RESIDUE ON ENGINE PARTS DURING MAINTENANCE, REPAIR AND OVERHAUL	<a href="#">3</a>
4	AIRBUS	IL S&S 2020_07#1 - 00	01.07.2020	ALL AIRBUS PRODUCTS	GENERAL INFORMATION LETTER	<a href="#">4</a>
5	BHTC	OSN GEN-20-50 NEW ISSUE	07.07.2020	ALL BHTC PRODUCTS	COCKPIT AND CABIN PASSENGER SAFETY	<a href="#">5</a>
6	AIRBUS	SPN NO. 3535-P-00 REV. 0	10.07.2020	ALL AIRBUS PRODUCTS	NEW RELEASE OF THE "Together4Safety" WEBSITE BY THE EASA	<a href="#">6</a>
7	AIRBUS	SPN NO. 3550-P-00 REV. 0	03.08.2020	ALL AIRBUS PRODUCTS	SAFETY ADVICES AND TIPS FOR PILOTS RETURNING POST COVID-19	<a href="#">7</a>
8	LEONARDO	ISSUE 37TH	02.07.2020	AW139	AW139 INTERACTIVE ELECTRONIC TECHNICAL PUBLICATION (IETP)	<a href="#">8</a>
9	LEONARDO	IL AW139-20-107 IL A119-20-070 IL A109S-20-072 IL A109E-20-085 IL AW189-20-026	13.07.2020	AW139/A119/A109E/A109S	ELIGIBILITY FOR LEONARDO HELICOPTERS PRODUCTS TO CAT.POL.H.305	<a href="#">9</a>
10	LEONARDO	TMI 139-497 NEW ISSUE	10.07.2020	AW139	RW LONGERON – SPECIFIC REPAIR PROCEDURE	<a href="#">10</a>

NO.	VENDOR	REF. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
11	LEONARDO	TMI NO. 139-528 NEW ISSUE	17.07.2020	AW139	REPLACEMENT OF LH UPPER T-SHAPE PROFILE P/N 3P5333A18651 STA 5700 - STA 6700, BL - 550, WL 2670	<a href="#">11</a>
12	LEONARDO	IL AW139-20-108 NEW ISSUE	29.07.2020	AW139	HUMS MISS DATA ARISING PERIODICITY ALLIGNMENT	<a href="#">12</a>
13	LEONARDO	DOC. NO.: 139G0290X002 ISSUE 2 REV. 26	02.07.2020	AW139	ROTORCRAFT FLIGHT MANUALS	<a href="#">13</a>
14	LEONARDO	ISE NO. 139-020 NEW ISSUE	30.07.2020	AW139	LIFE RAFT INSTALLATION/INSPECTION - RELEASE OF ALERT SB 139-648	<a href="#">14</a>
15	LEONARDO	DOC. NO.: 139G0000N027 ISSUE B	01.06.2020	AW139	OSD - FCD PUB. CODE: 502500071	<a href="#">15</a>
16	LEONARDO	IL AW189-20-027 NEW ISSUE	29.07.2020	AW189	HUMS MISS DATA ARISING PERIODICITY ALLIGNMENT	<a href="#">16</a>
17	LEONARDO	CHAPTER 00 - ISSUE 007 CHAPTER 04 - ISSUE 019 CHAPTER 05 - ISSUE 026	CHAPTER 00- 08.06.2020 CHAPTER 04- 09.06.2020 CHAPTER 05- 08.06.2020	AW189	AW189 AIR VEHICLE MAINTENANCE PLANNING INFORMATION (AMPI)	<a href="#">17</a>
18	LEONARDO	DOC. NO.: 189G3360A001 ISSUE N	26.05.2020	AW189	AW189 NVG-CRH PUB. CODE: 502189054	<a href="#">18</a>
19	LEONARDO	DOC. NO.: 189G0000A002 ISSUE Q	05.2020	AW189	AW189 KIT-CRH PUB. CODE: 502189052	<a href="#">19</a>
20	LEONARDO	DOC. NO.: 189G9850A005 REV. B	27.05.2020	AW189	AW189 PEDS-CRH PUB. CODE: 502189072	<a href="#">20</a>
21	LEONARDO	DOC. NO.: 189G0000A002/ 01 ISSUE A	05.2020	AW189	AW189 KIT-CRH ENGINE PUB. CODE: 502189052	<a href="#">21</a>
22	LEONARDO	ISE NO. 189-015 NEW ISSUE	31.07.2020	AW189	TAIL ROTOR FLIGHT CONTROLS - IMPROVEMENTS	<a href="#">22</a>
23	LEONARDO	MANUAL PART NO. 3043322 REV. 39.0	20.07.2020	PW206C	PW206C MAINTENANCE MANUAL	<a href="#">23</a>
24	AIRBUS	IN NO. 3481-I-00 REV. 0	06.07.2020	EC155/EC120B	THE MARKETPLACE: AN AIRBUSWORLD eORDERING SERVICE	<a href="#">24</a>
25	AIRBUS	SPN NO. 3195-P-00 REV. 1	07.07.2020	EC155/EC120B	ESPN-R-HOIST TASK FORCE RECOMMENDATIONS AND	<a href="#">25</a>

NO.	VENDOR	REF. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
					AIRBUS HELICOPTERS ADDITIONAL NOTES	
26	SAFRAN	X 292 N4 450 2 UPDATE NO. 46	15.06.2020	ARRIEL 2C1	ARRIEL 2C1 MAINTENANCE MANUAL	<a href="#">26</a>
27	SAFRAN	X 292 N4 700 2 UPDATE NO. 44	15.06.2020	ARRIEL 2C1	ARRIEL 2C1 SPARE PARTS CATALOGUE	<a href="#">27</a>
28	SAFRAN	X 292 N4 800 2 UPDATE NO. 34	15.06.2020	ARRIEL 2C1	ARRIEL 2C1 MAINTENANCE TOOLS CATALOGUE	<a href="#">28</a>
29	SAFRAN	X 292 N4 450 2 UPDATE NO. 46	15.06.2020	ARRIEL 2C1	ARRIEL 2C1 TROUBLESHOOTING	<a href="#">29</a>
30	AIRBUS	SIN NO. 3543-S- 28 REV. 0	16.07.2020	EC155/EC120B	FUEL SYSTEM - RECOMMENDATION ON THE USAGE OF KATHON FP1.5 BIOCIDE BY DUPONT	<a href="#">30</a>
31	AIRBUS	IN NO. 3533-I- 62 REV. 0	23.07.2020	EC155	MAIN ROTOR - SWASHPPLATE LUBRICATION WITH CM15 GREASE	<a href="#">31</a>
32	AIRBUS	IN NO. 3140-I- 00 REV. 4	31.07.2020	EC155	ATA 63 - IMPROVEMENT OF THE HANDLING AND LOGISTICS OF SELECTED DYNAMIC COMPONENTS	<a href="#">32</a>
33	BHTC	PMC-429- 97499-02000-00 ISSUE 004	15.07.2020	429	429 MAINTENANCE MANUAL (MM)	<a href="#">33</a>
34	BHTC	PMC-429- 97499-01000-00 ISSUE 003	15.07.2020	429	429 MAINTENANCE PLANNING INFORMATION (MPI)	<a href="#">34</a>
35	BHTC	PMC-429- 97499-01000-00 ISSUE 004	27.07.2020	429	429 MAINTENANCE PLANNING INFORMATION (MPI)	<a href="#">35</a>
36	TEXTRON AVIATION	VERSION 2020.07.01	01.07.2020	B300	1VIEW OFFLINE APPLICATION	<a href="#">36</a>
37	TEXTRON AVIATION	FMS 130- 590031-199 REV. 5	01.12.2019	B300	FLIGHT MANUAL SUPPLEMENT - AIRPLANE REGISTERED IN CANADA	<a href="#">37</a>
38	TEXTRON AVIATION	ME-TP-0021 NEW ISSUE	07.2020	B300	ATA 34 - KING AIR WEATHER RADAR	<a href="#">38</a>
39	PRATT AND WHITNEY CANADA	CHAPTER 4 - REV. 26.0 CHAPTER 5 - REV. 26.0	23.03.2020	PT6B-37A	PT6B-37A MAINTENANCE MANUAL	<a href="#">39</a>

Kindly reminder to all,

- a) Refer to item no. 8, this IETP is a new issue not a revision. So, you need to uninstall the previous IETP then you may install the new one.
  
- b) Refer to item no. 36, this application is the new version of 1VIEW. For those who already installed 1VIEW (Offline) in laptop/PC, you just need to choose 1VIEW UPDATE folder (as per attached) and click the setup for patch installation. No need password required. For those who are never install 1VIEW application, you need to choose 1VIEW NEW INSTALL folder (as per attached). Kindly ask the username and password from Technical Publication.
  
- c) For item no. 23, you need to install the Winzip file (as per attached) into Pratt and Whitney Canada ETP, respectively.

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately. Software can be download from GAM Server

Thank You.



**NUR NABILLA BT. MOHD HASNAN**  
**TECHNICAL PUBLICATION**  
**GALAXY AEROSPACE (M) SDN. BHD.**