

## CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

<b>TO:</b> GAM AMO Dept, GAM CAMO Dept.	<b>FROM:</b> Technical Publication
<b>CC:</b> GAM AM, GAM QAM	<b>DATE:</b> 13.07.2021
<b>REFERENCE NO.:</b> CAMO/MEMO/2021/47	


Dear all,

Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement and to take action.

NO.	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1.	AIRBUS	SIN NO. 3700-S-24 REVISION 0	12.07.2021	EC120B EC155B	ELECTRICAL POWER - INFORMATION ABOUT FUSES POTENTIALLY CONTAINING ASBESTOS MATERIAL	<a href="#">1</a>
2.	LEONARDO	CHAPTER 00 - ISSUE 009 CHAPTER 04 - ISSUE 022 CHAPTER 05 - ISSUE 027	26.04.2021 03.03.2021 22.12.2020	AW189	AW189 AIR VEHICLE MAINTENANCE PLANNING INFORMATION (AMPI)	<a href="#">2</a>

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

*Thank you and stay safe!*



**NUR NABILLA MOHD HASNAN**  
**TECHNICAL PUBLICATION,**  
**CAMO DEPARTMENT,**  
**GALAXY AEROSPACE (M) SDN. BHD.**