

## CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

<b>TO:</b> GAM AMO Dept, GAM CAMO Dept.	<b>FROM:</b> Technical Publication
<b>CC:</b> GAM AM, GAM QAM	<b>DATE:</b> 30.08.2021
<b>REFERENCE NO.:</b> CAMO/MEMO/2021/61	

Dear all,


Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement and to take action.

NO.	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1.	FAA	SAIB AIR-21-14 NEW ISSUE	24.08.2021	R44	ROBINSON R44 AND R66 HELISAS AUTOPILOT/GARMIN PRIMARY FLIGHT DISPLAY (PFD) INTERFACE	<a href="#">1</a>
2.	TCCA	CASA 2021-12 ISSUE 01	24.08.2021	-	LOW PRESSURE FLEXIBLE OXYGEN HOSE CRACKING	<a href="#">2</a>
3.	LEONARDO	TMI NO. 139- 547 NEW ISSUE	19.08.2021	AW139	ANTI-TORQUE BEAM FITTINGS (STA 5100) - SPECIAL REPAIR PROCEDURE	<a href="#">3</a>
4.	LEONARDO	TMI NO. 139- 421 REV. F	23.08.2021	AW139	LEFT/RIGHT FRAME STA 5700 P/N 3P5338A13355/3P5338A13455 INSTALLATION PROCEDURE	<a href="#">4</a>
5.	LEONARDO	ISSUE 2 REV. 9	21.07.2021	AW189	AW189 QUICK REFERENCE HANDBOOK	<a href="#">5</a>
6.	LEONARDO	DOC. NO.:189G0000 A002/01 ISSUE C	30.04.2021	AW189	AW189 COMPATIBILITY REFERENCE HANDBOOK FOR GE ENGINE PUB. CODE: 502189052	<a href="#">6</a>

7.	LEONARDO	DOC. NO.:189G0000 A002 ISSUE S	28.07.2021	AW189	AW189 COMPATIBILITY REFERENCE HANDBOOK PUB. CODE: 502189052	<a href="#">7</a>
8.	LYCOMING	SI NO. 1037 REVISION Y	25.08.2021	O-540-F1B5	APPROVED PISTONS, RINGS, CYLINDERS AND GASKET SET APPLICATION FOR USE ON LYCOMING AIRCRAFT ENGINES	<a href="#">8</a>

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

*Thank you and stay safe!*



**NUR NABILLA MOHD HASNAN**  
**TECHNICAL PUBLICATION,**  
**CAMO DEPARTMENT,**  
**GALAXY AEROSPACE (M) SDN. BHD.**