

CONTINUING AIRWORTHINESS MANAGEMENT ORGANISATION MEMO

TO: GAM AMO Dept, GAM CAMO Dept.	FROM: Technical Publication
CC: GAM AM, GAM QAM	DATE: 25.04.2022
REFERENCE NO.: CAMO/MEMO/2022/32	

Dear all,


Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement and to take action.

NO.	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1.	LEONARDO	TMI NO. 109-459 REV. B	20.04.2022	A109E	PRODUCTION FLIGHT ACCEPTANCE TEST PROCEDURE	1
2.	LEONARDO	SIL NO. S-GEN-22- 001 NEW ISSUE	20.04.2022	ALL LEONARDO PRODUCTS	OPERATIONAL TRAINING	2
3.	LEONARDO	MANUAL NO. MAN- 3G1200G00431 REV. A	22.03.2022	AW139	UPPER DECK MAINTENANCE STEP P/N 3G1200G00431	3
4.	LEONARDO	MANUAL NO. MAN- 3G1200G01131 REV. A	22.03.2022	AW139	UPPER DECK MAINTENANCE STEP FOR OPLS P/N 3G1200G01131	4
5.	LEONARDO	MANUAL NO. PEC-0139-MAN- 0017-00 NEW ISSUE	24.01.2022	AW139	TOW BAR ASSY FOR AW139 WITH FLIR LEOSS/WESCAM AND PAD/SKI P/N 3G0910G00231	5
6.	AIRBUS	SIN NO. 3786-S-62 REV. 0 ERRATA CORRIGE	15.04.2022	EC120B EC155B	MAIN ROTOR – TRACK AND BALANCE ADJUSTMENT DIFFICULTY	6

7.	CAAM	CAN 005/2022 ISSUE 01	22.04.2022	ALL OPERATORS IN MALAYSIA	NOTICE OF PROPOSED RULE MAKING: NEW CADs EFFECTIVE 15TH MAY 2022	7
8.	GENERAL ELECTRIC	IC 70-48-22-015 SPM REVISION 111	22.042022	CT7-2E1	INCREMENTAL CHANGES - REPLACEMENT OF RING-LOCK SELF-LOCKING INSERT	8

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

Thank you and stay safe!



NUR NABILLA MOHD HASNAN
TECHNICAL PUBLICATION,
CAMO DEPARTMENT,
GALAXY AEROSPACE (M) SDN. BHD.