

CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

TO: GAM AMO Dept, GAM CAMO Dept.	FROM: Technical Publication
CC: GAM AM, GAM QAM	DATE: 10.03.2023
REFERENCE NO.: CAMO/MEMO/2023/19	

Dear all,

Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer to all publications below for your acknowledgement and to take action.

NO.	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1	CAAM	SI 05/2023 NEW ISSUE	10.03.2023	ALL OPERATORS IN MALAYSIA	AWARENESS ON SAFETY CULTURE IN AVIATION PERSONNEL	1
2	EASA	SIB NO. 2023- 023 NEW ISSUE	09.03.2023	ALL OPERATORS IN MALAYSIA	INCORRECT BAROMETRIC ALTIMETER SETTING	2
3	ROBINSON	RTR 661	23.12.2022	R66	PILOT'S OPERATING HANDBOOK	3
4	HARTZELL	HC-SL-61-374 NEW ISSUE	08.03.2023	HC-B4MP-3C	ONLINE PRODUCT REGISTRATION	4
5	GENERAL ELECTRIC	SPM 70-00- 99-030-752 REV 111	08.03.2023	CT7-2E1	INCREMENTAL CHANGE - CONSUMABLE MATERIALS - THIN FILM SULFURIC ACID ANODIZING HEXAVALENT CHROMIUM FREE SEALING SOLUTION	5
6	GENERAL ELECTRIC	SPM 70-80- 03-015 REV 111	08.03.2023	CT7-2E1	INCREMENTAL CHANGE - CONSUMABLE PRODUCTS - FINISHES AND PROTECTIVE COATINGS	6
7	GENERAL ELECTRIC	SPM 70-45- 06-015 REV 111	08.03.2023	CT7-2E1	INCREMENTAL CHANGE - THIN FILM SULFURIC ACID ANODIZING	7

8	GENERAL ELECTRIC	SPM 70-42-00-015 REV 111	08.03.2023	CT7-2E1	INCREMENTAL CHANGE - BLENDING AND REMOVAL OF HIGH METAL PROCEDURES	8
9	LEONARDO	ISSUE 2 REVISION 11 ERRATA CORRIGE	06.03.2023	AW189	AW189 ROTORCRAFT FLIGHT MANUAL DOC. REF. NO.: 189G0290X002	9A 9B
10	FAA	SAIB 2023-03 NEW ISSUE	08.03.2023	ALL OPERATORS IN MALAYSIA	ROTORCRAFT CRASH RESISTANT FUEL SYSTEMS	10
11	TEXTRON	MTL-56-01 NEW ISSUE	06.03.2023	B300	WINDOWS - WINDOW SHADE DUST PANE BONDING IMPROVEMENT	11
12	LEONARDO	SIL NO: S-GEN-23-001 NEW ISSUE	03.03.2023	ALL LEONARDO HELICOPTER PRODUCTS	UNSERVICEABLE PARTS' RECALL	12
13	AIRBUS	REVISION 12	30.01.2023	EC155B	MASTER SERVICING MANUAL (MSM)	13
14	AIRBUS	REVISION 12	30.01.2023	EC155B1	MASTER SERVICING MANUAL (MSM)	14
15	AIRBUS	REVISION 9	30.01.2023	EC155B1	AIRWORTHINESS LIMITATIONS SECTION (ALS)	15
16	LYCOMING	SI. NO. 1577A REV. A	25.01.2023	I0-540-AE1A5	INTAKE VALVE IN-SERVICE DATA	16

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

Thank you and stay safe!



DEANNA IZZATY BINTI AHMAD SHOUIK
TECHNICAL PUBLICATION,
CAMO DEPARTMENT,
GALAXY AEROSPACE (M) SDN. BHD.