

## CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

<b>TO:</b> GAM AMO Dept, GAM CAMO Dept.	<b>FROM:</b> Technical Publication
<b>CC:</b> GAM AM, GAM QAM	<b>DATE:</b> 8.5.2023
<b>REFERENCE NO.:</b> CAMO/MEMO/2023/33	

Dear all,

Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer to all publications below for your acknowledgement and to take action.

NO.	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1	SAFRAN	DOC. REF. X 319 L6 301 2 UPDATE NO. 48	15.04.2023	ARRIUS 2F	MAINTENANCE MANUAL	<a href="#">1</a>
2	SAFRAN	DOC. REF. X 319 L6 700 2 UPDATE NO. 45	15.04.2023	ARRIUS 2F	SPARE PARTS CATALOGUE	<a href="#">2</a>
3	SAFRAN	DOC. REF. X 319 L6 800 2 UPDATE NO. 33	15.04.2023	ARRIUS 2F	MAINTENANCE TOOLS CATALOGUE	<a href="#">3</a>
4	SAFRAN	DOC. REF. X 319 L6 301 2 UPDATE NO. 48	15.04.2023	ARRIUS 2F	TROUBLESHOOTING	<a href="#">4</a>
5	ROBINSON	SL-67 REV B	28.04.2023	R44	COMPONENT MAINTENANCE COURSE	<a href="#">5</a>
6	ROBINSON	SL-25 REV B	28.04.2023	R66	COMPONENT MAINTENANCE COURSE	<a href="#">6</a>
7	LEONARDO	TMI 139-566 NEW ISSUE	27.04.2023	AW139	TAIL ROTOR HEAD INSTALLATION	<a href="#">7</a>
8	LEONARDO	DOC. NO.:189G3360 A001 ISSUE S	27.04.2023	AW189	NVG COMPATIBILITY REFERENCE HANDBOOK PUB. CODE: 502189054	<a href="#">8</a>
9	LEONARDO	TIL NO. T-139- 23-004 REV. A	05.05.2023	AW139	TAIL BOOM ASSY CORROSION PREVENTION IMPROVEMENT	<a href="#">9</a>

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

*Thank you and stay safe!*



**DEANNA IZZATY BINTI AHMAD SHOUIK  
TECHNICAL PUBLICATION,  
CAMO DEPARTMENT,  
GALAXY AEROSPACE (M) SDN. BHD.**