

## CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO TO: GAM AMO Dept, GAM CAMO Dept. FROM: Technical Publication CC: GAM AM, GAM QAM DATE: 16.06.2023 REFERENCE NO.: CAMO/MEMO/2023/41

Dear all,

Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer to all publications below for your acknowledgement and to take action.

NO.	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1	LEONARDO	ISSUE 34 NEW ISSUE	06.06.2023	A109E	INTERACTIVE ELECTRONIC TECHNICAL PUBLICATION (IETP)	<u>1</u>
2	LEONARDO	SIL NO: S-139-23-003 NEW ISSUE	15.06.2023	AW139	SERVICE INFORMATION LETTER HONEYWELL TRANSITION WEATHER RADAR PRIMUS 660 PRODUCT LINE TO ONTIC	<u>2</u>
3	HARTZELL	HC-SL-61-375 NEW ISSUE	02.06.2023	HC-B4MP-3C	SERVICE LETTER TANIS AIRCRAFT PRODUCTS/HARTZELL PROPELLER INC. PART NUMBER CROSS- REFERENCE	<u>3</u>
4	PRATT AND WHITNEY CANADA	SIL NO. GEN-038 REV 4	13.06.2023	ALL PRATT AND WHITNEY CANADA PRODUCTS	SERVICE INFORMATION LETTER USE OF NON-PRATT & WHITNEY CANADA (P&WC) SUPPORTED PARTS OR NON- P&WC APPROVED REPAIR SCHEMES.	4



5	PRATT AND WHITNEY CANADA	SIL NO. GEN-034 REV 4	13.06.2023	ALL PRATT AND WHITNEY CANADA PRODUCTS	SERVICE INFORMATION LETTER ENGINE MAINTENANCE AT OTHER THAN PRATT & WHITNEY CANADA CORP. ("P&WC") RECOMMENDED TIME BETWEEN OVERHAUL ("TBO")/HOT SECTION INSPECTION ("HSI")/PERIODIC MAINTENANCE INTERVALS AND THE EFFECT ON WARRANTY.	<u>5</u>
6	LEONARDO	TMI 189-048 NEW ISSUE	08.06.2023	AW189	TEMPORARY MAINTENANCE INSTRUCTION LEFT BL 550 AFT LONGERON - REPLACEMENT (REMOVE AND INSTALL A NEW ITEM)	<u>6</u>

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) affected immediately.

Thank you and stay safe!

NOR'IZZAH BINTI HASHIM

CAMO TECHNICAL PUBLICATION,

CAMO DEPARTMENT,

GALAXY AEROSPACE (M) SDN. BHD.