

## CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO TO: GAM AMO Dept, GAM CAMO Dept. FROM: Technical Publication CC: GAM AM, GAM QAM DATE: 08.03.2024 REFERENCE NO.: CAMO/MEMO/2024/25

Dear all,

Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer to all publications below for your acknowledgement and to take action.

NO ·	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1.	MYSAFT	SIL NO: SIL 0315 REV 0	13.11.2015	ALL MYSAFT BATTERIES PRODUCTS	USE OF REPLACEMENT PARTS	1
2.	LEONARDO	TMI 139-429 REV H	29.02.2024	AW139	FORWARD LOWER PANEL ASSEMBLY - REMOVE AND REPLACE - 3P5340A01431 AND 3P5340A43631	2
3.	LEONARDO	ISEN-24-006 NEW ISSUE	05.03.2024	AW139	IN-SERVICE EVENT IN MALAYSIA	3
4.	EASA	SIB NO. 2024-04 NEW ISSUE	06.03.2024	ALL OPERATORS IN MALAYSIA	RISKS FROM USING HIGH POWER LIGHTS CLOSE TO AIRCRAFT STRUCTURES	4
5.	CAAM	SI 06/2024 NEW ISSUE	06.03.2024	ALL OPERATORS IN MALAYSIA	OPTIMIZING AVIATION SAFETY THROUGH NAVIGATING HUMAN PERFORMANCE, LIMITATION AND AIRCRAFT CAPABILITIES	<u>5</u>



NO ·	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
6.	HARTZELL	REV. 22	March 2024	HC-B4MP-3C	PROPELLER OWNER'S MANUAL AND LOGBOOK DOC. REF.: MANUAL NO. 139 (61-00-39)	<u>6</u>
7.	AIRBUS	DN NO: DN.008.0023.1 REV 1	29.02.2024	EC120B	TECH DATA – COMPLEMENTARY INSTRUCTIONS FOR CONTINUED AIRWORTHINESS (ICA)	7

Please be advise, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

Thank you and stay safe!

DEANNA IZZATY BINTI AHMAD SHOUFIK **TECHNICAL PUBLICATION**,

CAMO DEPARTMENT,

GALAXY AEROSPACE (M) SDN. BHD.