

## CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

<b>TO:</b> GAM AMO Dept, GAM CAMO Dept.	<b>FROM:</b> Technical Publication
<b>CC:</b> GAM AM, GAM QAM	<b>DATE:</b> 18.03.2024
<b>REFERENCE NO.:</b> CAMO/MEMO/2024/31	

Dear all,

Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer to all publications below for your acknowledgement and to take action.

NO	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1.	EASA	SIB NO. 2024-05 NEW ISSUE	13.03.2024	ALL OPERATORS IN MALAYSIA	INCORRECT COMPUTATION OF THE HYBRID FLIGHT PATH ANGLE BY LCR-100 ATTITUDE HEADING REFERENCE SYSTEM	<a href="#">1</a>
2.	PRATT AND WHITNEY CANADA	SIL NO. GEN-065 REV 2	13.03.2024	ALL PRATT AND WHITNEY CANADA PRODUCTS	INFORMATION REQUIRED TO PROCESS NEW ENGINE ACCESSORY WARRANTY CLAIMS	<a href="#">2</a>
3.	LEONARDO	SIL NO: S-139-24-002 NEW ISSUE	15.03.2024	AW139	NEW MANAGEMENT FOR COMPONENT REPAIR & OVERHAUL PUBLICATION	<a href="#">3</a>
4.	LEONARDO	SIL NO: S-189-24-002 NEW ISSUE	15.03.2024	AW189	NEW MANAGEMENT FOR COMPONENT REPAIR & OVERHAUL PUBLICATION	<a href="#">4</a>

NO	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
5.	LEONARDO	SIL NO: S-109E-24-002 NEW ISSUE	15.03.2024	AW109E	NEW MANAGEMENT FOR COMPONENT REPAIR & OVERHAUL PUBLICATION	<a href="#">5</a>
6.	LEONARDO	SIL NO: S-139-24-003 NEW ISSUE	15.03.2024	AW139	INSPECTION OF MAIN LANDING GEAR (MLG) SHOCK ABSORBER PISTON ROD EYE END – NOTICE OF RELEASE OF SB	<a href="#">6</a>
7.	LEONARDO	ISSUE 2 REV. 28 ERRATA CORRIGE	14.03.2024	AW139	QUICK REFERENCE HANDBOOK DOC REF. NO.: 139G0290X002	<a href="#">7</a>

Please be advise, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

*Thank you and stay safe!*



**DEANNA IZZATY BINTI AHMAD SHOUIK**  
**TECHNICAL PUBLICATION,**  
**CAMO DEPARTMENT,**  
**GALAXY AEROSPACE (M) SDN. BHD.**