

AMO MEMO

REF NO.:	GAM/WKSP/24/002			
TO:	All AMO Personnel and Calibration Laboratory			
FROM:	Workshop In Charge (WIC)			
DATE:	28 August 2024			
RE:	New Revision of Calibration Technical Procedures (CL-TP) Issue 2 Rev.0 and Revised Calibration Forms			

This memo is to announce that a new revision for Calibration Technical Procedures, issue 2 Rev.0 and Revised Calibration Forms has been uploaded to GAMS Portal. Kindly discard the previous version of the manual and forms.

Below is the summary of amendment for your kind information.

Please log in GAMs Portal to view the document.

Document reference: GAM/CL-TP/Issue 2, Revision 0. and Calibration Forms.

Doumet Reference	Issue No	Rev No	Details of change
GAM/CL-TP	2	0	*1.1 Procedure updated and added new procedure. *1.1.2-vii the word location removed and added serial number, status and remarks. *Calibration device standard for hand torque tool single transducer Part no. updated. *General mathematical model for pressure calibration and uncertainty due to readability for digital pressure gauge added. *A general mathematical model and additional uncertainty source added for dimensional calibration. *Updated and added new references, procedure and table for force verification. *All calibration and verification method form section updated. *Company new LOGO.
GAM/CL-F30	-	1	Company new LOGO.
GAM/CL-F31	-	1	*Company new LOGO.
GAM/CL-F32	-	1	*Company new LOGO.
GAM/CL-F33	-	1	*Company new LOGO.
GAM/CL-F34	-	1	*Company new LOGO.
GAM/CL-F35	-	1	*Company new LOGO.

Thank You.

- END -

GALAXY AEROSPACE (M) SDN.BHD.

Management Office: No. A-01-02, Blok A, Bangunan Perdagangan Siera Ara Damansara, Jalan PJU 1A/5A, Ara Damansara, 47301 Petaling Jaya, Selangor Darul Ehsan, Malaysia.

AMO Office: Suite 11-14, Helicopter Centre, Malaysia Interna®onal Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor Darul Ehsan, Malaysia. Hangar Address: Hangar 2, UniKL-MIAT, Persiaran A, Off Jalan Lapangan Terbang Subang, 47200 Subang, Selangor Darul Ehsan, Malaysia. Tel: +603 7455 0555 Fax: +603 7734 7526