

AMO MEMO

REF NO. :	GAM/WKSP/24/006
TO:	All AMO Personnel
FROM:	Engineering Manager.
DATE:	27 Sept 2024
RE:	New Revision of WORKSHOP WORKSHEET (GAM/E-001C REV2) AND WORKSHOP PROCESS REPORT (GAM/E-029 REV1).

This message is to announce that a new revision of WORKSHOP WORKSHEET (GAM/E-001C REV2) AND WORKSHOP PROCESS REPORT (GAM/E-029 REV1) has been uploaded to GAMS Portal.

Below is the summary of amendment for your kind information.

Please log in GAMs Portal to view the document.

Document reference:

- 1. WORKSHOP WORKSHEET (GAM/E-001C REV2).
- 2. WORKSHOP PROCESS REPORT (GAM/E-029 REV1).

Domet Reference	Issue No	Rev No	Details of change
GAM/E-001C	-	2	 Change of company logo. Inclusion of CAAM Part-145 Approval Number Column. Inclusion of instructions for completing GAM/E-001C-Workshop Worksheet.
GAM/E-029	-	1	 Change of company logo. Inclusion of FAA 8130-3. Technical Directives change to Service Order. Corrections on instructions for completing GAM/E-029-Workshop Process Report.

Thank You.

- END -

GALAXY AEROSPACE (M) SDN.BHD.

Management Office: No. A-01-02, Blok A, Bangunan Perdagangan Siera Ara Damansara, Jalan PJU 1A/5A, Ara Damansara, 47301 Petaling Jaya, Selangor Darul Ehsan, Malaysia.

AMO Office: Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor Darul Ehsan, Malaysia. Hangar Address: Hangar 2, UniKL-MIAT, Persiaran A, Off Jalan Lapangan Terbang Subang, 47200 Subang, Selangor Darul Ehsan, Malaysia. Tel: +603 7455 0555 Fax: +603 7734 7526