		yAerospace	Galaxy Aerospace (M) Sdn. Bhd, (1040262-D) No 79-1, 1st floor, Jln PJU 1A/41B, 47301 Petaling Jaya, Selangor Darul Ehsan, Malaysia.			HIRARC REGISTER				Document No.: GALAXY-HSE-SMS Release date: 12 Feb 2019 SMS Page: APPENDIX C		
HIRARC NO.: GAM/SMS/H-60(19)				Date conducted: 12 Feb 2019		Conducted by: Nizam (S			Nizam (SM)	Approved by:	Mohammad Nizam Jaafar	
Pro	cess/ Location:	New CAMO capability (AS365 N2)		Revision:	0	Received By:		Salman (QAM)	Signature:	Deijn		
	Hazard Identification					Risk Assessment			ssment		Risk Control	
No.		Workplace/ Activity	Hazard		Consequences/ Effects	Likeli- hood	Severity	Risk Rating	Existing Risk Control (if any)	Recommended and additional Control	PIC	Status/ Remarks
1	Insert picture here	To add AS365 N2 in CAMO capability list, to obtain CAAM Approval to manage the continuing Airworthiness belongs to Danga Bay	Transition of capability upgraded will implicate interest of the company with non-compliance with authority regulation		The company can't achieve their business opportunities and commercial values	4	D	4D	Admin. Control: Refer to SMS Manual Part 14.2 (Process of management of change MOC)	Admin. Control: Identify gaps and weaknesses thru MOC tracking to ensure the achievement	QAM SM	Risk reduced to 2D after additional control measure and found on acceptable level
2	Insert picture here	To nominated and qualify new ARS personal and adequate man power on the planning, tech records and publication section.	the comp compliance regulation manpower	cate interest of pany with non- e with authority on and lag of r to support the eration	Difficulty to perform a task as per job assigned and will implicated the a/c operation	3	E	3E	Admin. Control: Refer to AN 6102 Para 10.2	Admin. Control: Identify gaps and weaknesses to ensure the achievement	QAM CAM	Risk reduced to 1E after an additional control measure and found was on acceptable level
3	Insert picture here	An appropriate training have to attend by nominated ARS and CAMO staff	perform function c adequate	on of ability to a prescribed due to lack and training as per equired	Difficulty to perform a task as per job assigned and will implicated the a/c operation	2	E	2E	Admin. Control: Refer to MOE Part 3.4.5 (Training and continuation training)	Admin. Control: General Familiarization course on aircraft AS365 required	QAM CAM	Risk reduced to 1E after an additional control measure and found on acceptable level
4	Insert picture here	Required a work station for maintenance planning and storage area and locker for aircraft record	facilities unsaf environme affe	or poor storage will expose to fe working nt which lead to ected the mentation	improper storage of aircraft	4	D	4D	Admin. Control: Refer to MOE Part 2.14.2 (Technical record control)	Admin. Control: To carried out observation and surveillance to ensure the documentation is well kept	QAM SM	Risk reduced to 2D after additional control measure and found on acceptable level