

PERMIT TO FLY (PTF) MASTERLIST 2021



| NO | PTF REF NO | AC REG | REASON FOR PTF | PTF ISSUE DATE | ISSUED BY | RECEIPT NO | REMARKS |
|----|------------------|--------|---|----------------|----------------------------|---------------|----------|
| 1 | PTF/9M-AMA/21/01 | 9M-AMA | SPECIAL INSTRUCTIONS FOR REASSEMBLING AND FLIGHT TESTING R44 SERIES HELICOPTERS AFTER CRATING FOR EXPORT (WP-AMA-20-2518) | 08.01.2021 | ARS 04: ROSLINA SOBRI | A1048136 - 02 | APPROVED |
| 2 | PTF/9M-BOC/21/02 | 9M-BOC | TAIL ROTOR BLADE REPLACEMENT - BLADE TRACK AND BALANCE CHECK POST REPLACEMENT | 01.02.2021 | ARS 03: ISMAIL SULAIMAN | A1048136 - 03 | APPROVED |
| 3 | PTF/9M-BOB/21/03 | 9M-BOB | MAIN ROTOR BLADE INSTALLATION | 09.02.2021 | ARS 01: HAIREE MAT | A1048136 - 04 | APPROVED |
| 4 | PTF/9M-BOE/21/04 | 9M-BOE | MAIN ROTOR LAG DAMPER REPLACEMENT | 10.02.2021 | ARS 03: ISMAIL SULAIMAN | A1048136 - 05 | APPROVED |
| 5 | PTF/9M-HFA/21/05 | 9M-HFA | 500 FH // 24 MTH AIRFRAME INSPECTION 500 FH // 24 MTH ENGINE INSPECTION | 09.02.2021 | ARS 01: HAIREE MAT | FOC | APPROVED |
| 6 | PTF/9M-PMD/21/06 | 9M-PMD | ANTI ROTATION BLOCK REPLACEMENT | 27.02.2021 | ARS 03: ISMAIL SULAIMAN | FOC | APPROVED |
| 7 | PTF/9M-PMF/21/07 | 9M-PMF | REASSEMBLY AFTER TRANSPORTATION (NEW AIRCRAFT) | N/A | ARS 03: ISMAIL SULAIMAN | FOC | CANCEL |
| 8 | PTF/9M-PMA/21/08 | 9M-PMA | POST MAIN ROTOR LAG DAMPER REPLACEMENT | 04.03.2021 | ARS 03: ISMAIL SULAIMAN | FOC | APPROVED |
| 9 | PTF/9M-BOD/21/09 | 9M-BOD | POST INSTALLATION NO.2 ENGINE | 15.3.21 | ARS 03: ISMAIL SULAIMAN | FOC | APPROVED |

| | | | | | | | |
|----|------------------|--------|---|------------|----------------------------|-----|----------|
| 10 | PTF/9M-PME/21/10 | 9M-PME | POST MAIN ROTOR WHITE DAMPER REPLACEMENT | 10.3.21 | ARS 03: ISMAIL SULAIMAN | FOC | APPROVED |
| 11 | PTF/9M-JPM/21/11 | 9M-JPM | POST INSTALLATION NO.1 & NO.2 ENGINES | 27.3.21 | ARS 03: ISMAIL SULAIMAN | FOC | APPROVED |
| 12 | PTF/9M-PMF/21/12 | 9M-PMF | NO.1 ENGINE INSTALLATION NO.2 ENGINE INSTALLATION | 2.4.21 | ARS 03: ISMAIL SULAIMAN | FOC | APPROVED |
| 13 | PTF/9M-PMD/21/13 | 9M-PMD | NO.1 PUMP OPERATIONAL TEST | 5.4.21 | ARS 03: ISMAIL SULAIMAN | FOC | APPROVED |
| 14 | PTF/9M-BOF/21/14 | 9M-BOF | POST MAIN ROTOR HEAD INSTALLATION | 11.04.2021 | ARS 03: ISMAIL SULAIMAN | FOC | APPROVED |
| 15 | PTF/9M-BOE/21./5 | 9M-BOE | POST 800 HOURS INSPECTION | 23.04.2021 | ARS 03: ISMAIL SULAIMAN | FOC | APPROVED |
| 16 | PTF/9M-BOC/21/16 | 9M-BOC | POST INSTALLATION MAIN ROTOR DAMPER ANTI ROTATION BLOCK | 22.04.2021 | ARS 03: ISMAIL SULAIMAN | FOC | APPROVED |
| 17 | PTF/9M-PTC/21/17 | 9M-PTC | - FLIGHT CONTROL CHECK / ASSESSMENT UPON COMPLETION OF PAINTING, BALANCING AND ADJUSTMENT. | 30.4.21 | ARS 02: Azillah Matap | FOC | APPROVED |
| 18 | PTF/9M-AMA/21/18 | 9M-AMA | POST 100 HOURS // 12 MONTHS INSPECTION | 05.05.2021 | ARS 04: ROSLINA SOBRI | FOC | APPROVED |
| 19 | PTF/9M-PMB/21/19 | 9M-PMB | - FUNCTIONAL FLIGHT CHECK AFTER PUMP INSTALLATION | 7.5.21 | ARS03: Ismail Sulaiman | FOC | APPROVED |

| | | | | | | | |
|----|------------------|--------|--|------------|----------------------------|-----|---|
| 20 | PTF/9M-PMD/21/13 | 9M-PMD | POST NO.2 HYDRAULIC PUMP AND LIP SEAL REPLACEMENT | 08.05.2021 | ARS 03: ISMAIL SULAIMAN | FOC | APPROVED |
| 21 | PTF/9M-BOD/21/21 | 9M-BOD | POST TAIL ROTOR LAG DAMPER REPLACEMENT | 18.05.2021 | ARS03: Ismail Sulaiman | FOC | APPROVED |
| 22 | PTF/9M-SAS/21/22 | 9M-SAS | MAIN ROTOR AND TAIL ROTOR TRACK AND BALANCE POST 4YRS INSPECTION | N/A | N/A | N/A | CANCEL (refer email from Hj.Hasnan dated 11/06/2021) |
| 23 | PTF/9M-PEC/21/23 | 9M-PEC | 2 YEARS INSPECTION - MAIN ROTOR HUB REMOVAL | TBA | ARS03: Ismail Sulaiman | FOC | TBA - PENDING sect A FROM ENGINEERING |
| 24 | PTF/9M-BOC/21/24 | 9M-BOC | TR DAMPER | 22/6/2021 | ARS03: Ismail Sulaiman | FOC | APPROVED |
| 25 | PTF/9M-BOB/21/25 | 9M-BOB | RTB DUE TO DEFECT VIBRATION DURING FLIGHT | 24/6/2021 | ARS01: Hairee Mat | FOC | APPROVED |
| 26 | PTF/9M-PMF/21/26 | 9M-PMF | MRB LAG DAMPER REPLACEMENT | 5/7/2021 | ARS05: Syafiq Ismail | FOC | APPROVED |
| 27 | PTF/9M-PMD/21/27 | 9M-PMD | HYDRAULIC PUMP NO.2 AND NO.4 SEAL REPLACEMENT | 15/7/2021 | ARS05: Syafiq Ismail | FOC | APPROVED |
| 28 | PTF/9M-PMD/21/28 | 9M-PMD | POST REPLACEMENT OF HYDRAULIC PUMP NO 1 SEAL | 26/7/2021 | ARS05: Syafiq Ismail | FOC | APPROVED |
| 29 | PTF/9M-BOE/21/29 | 9M-BOE | POST ANNUAL INSPECTION | TBA | ARS 03: ISMAIL SULAIMAN | FOC | TBA |

| | | | | | | | |
|----|------------------|--------|--|-----------|-----------------|-----|----------|
| 30 | PTF/9M-BOC/21/30 | 9M-BOC | 1) 1200FH inspection (MR damper blade installation) 2) Engine No. 1 installation 3) TR blade assy installation | TBA | TBA | FOC | TBA |
| 31 | PTF/9M-SAS/21/31 | 9M-SAS | POST REPLACEMENT OF ENGINE #1 FADEC | 11.8.2021 | ISMAIL SULAIMAN | FOC | APPROVED |
| 32 | | | | | | | TBA |
| 33 | PTF/9M-PME/21/33 | 9M-PME | TAIL ROTOR PITCH LINK ADJUSTMENT | 2/9/2021 | SYAFIQ ISMAIL | FOC | APPROVED |
| 34 | | | | | | | |
| 35 | PTF/9M-BOF/21/35 | 9M-BOF | POST REPLACEMENT OF MAIN ROTOR DAMPER | 15/9/2021 | ISMAIL SULAIMAN | FOC | APPROVED |