Solavy Assessment	AIRWORTHINESS DIRECTIVES (AD) / SERVICE BULLETIN (SB)	REFERENCE NO.	CAMO/ADSB/AW139/2024-06		
GalaxyAerospace	MONTHLY SUMMARY	DATE	4/7/2024		

AIRWORTHINESS DIRECTIVES (AD) / SERVICE BULLETIN (SB) ISSUANCE FOR MONTH OF JUNE 2024

	(A) THE STATE	75.375	2000		1720				THE STATE OF	MED TO	AIRCRA	AFT REGN. & COM	MPLIANCE		Teleston en						
								M7	72-01(31307)			M72-02(31315)			M72-03(31316)						
NO	SB/AD NO	ISSUE/	ISSUE/	ISSUE/ SUBJECT CLASSIFICATION/ COMPLIANCE TIME TIC NO.	TIC NO.	NO.1 ENG	NO.1 ENGINE (PCE-KB0742)			ENGINE (PCE-KE	0740)		NO.1 ENGINE (NI	u)	REMARKS						
	3B/AD NO	REVISION	REVISION DATE	Jource	CATEGORIES	COMPENSACE INFO		NO.2 ENGINE(PCE-KB0739)			NO.2 ENGINE(PCE-KB0732)				NO.2 ENGINE (NI	L)	newalks				
								APPLICABILITY	STATUS	WORKPACK REF NO	APPLICABILIT Y	STATUS	WORKPACK REF NO	APPLICABILIT Y	STATUS	WORKPACK REF NO					
			Language and the second					SERVICE B	ULLETIN (AIRF	FRAME)											
1	139-779	ISSUE		ATA 21 – ECS SHOCK ABSORBERS REMOVAL RETROMOD	OPTIONAL	AT CUSTOMER'S OPTION	TIC-AW139- 24-0053				NOT APPLICABLE	CLOSED	-	NOT APPLICABLE	CLOSED		NOT APPLICABLE DUE TO COMPONENT PART NUMBER				
2	139-778	ISSUE		ATA 55 – TAIL PLANE ROD ASSY INSTALLATION INSPECTION	RECOMMENDED	WITHIN AND NOT LATER THAN 300 FH AFTER ISSUANCE	TIC-AW139- 24-0055				AIRCRAFT M72-01 WITHDRAWN FROM				NOT APPLICABLE CLOSED			NOT APPLICABLE	CLOSED	•	NOT APPLICABLE DUE TO COMPONENT PART NUMBER
3	139-616	ISSUE	19-Jun-2024	ATA 53 - LOWER LH TAIL LONGERON INSPECTION AND REPAIR	RECOMMENDED	PART I: WITHIN AND NOT LATER THAN 6 MONTHS AFTER ISSUANCE PART II, III, IV: WITHIN AND NOT LATER THAN 600 FH OR 1 YEAR WHICHEVER OCCURS FIRST AFTER ACCOMPLISHMENT OF PART I	TIC-AW139- 24-0056	SERV	2-01 WITHDRA VICE (CRASHED		APPLICABLE	PART I: OPEN DUE 18/12/2024 PART II: OPEN NOT LATER THAN 600 FH OR 1 YEAR WHICHEVER FIRST AFTER COMPILANCE OF PART I	-	APPLICABLE	PART I: OPEN DUE 18/12/2024 PART II: OPEN NOT LATER THAN 600 FH OR 1 YEAR WHICHEVER FIRST AFTER COMPILANCE OF PART I		PART I: APPLICABLE DUE TO AIRCRAFT FITTED WITH COMPONENT PART II: APPLICABLE DUE TO AIRCRAFT FITTED WITH COMPONENT PART III & IV: NOT APPLICABLE DUE TO PART NUMBER NOT INCLUDED				
					191			SERVICE	BULLETIN (EN	NGINE)											
1	NIL							AIRCRAFT M72	2-01 WITHDRA VICE (CRASHED		NIL				NIL		NIL				
								AIRWORTHINE	SS DIRECTIVE	(AIRFRAME)											
1	2024-0107	ISSUE	7-Jun-2024	ATA 25 – EQUIPMENT / FURNISHINGS – MEDICAL EQUIPMENT SUPPORT – INSPECTION	EASA AD	WITHIN 30 FH OR 30 DAYS WHICHEVER OCCURS FIRST AFTER ISSUANCE	TIC-GEN-24 0023		2-01 WITHDRA VICE (CRASHED	The second second	NOT APPLICABLE	CLOSED	-	NOT APPLICABLE	CLOSED		NOT APPLICABLE TO AIRCRAFT TYPE AND SERIAL NUMBER				



AIRWORTHINESS DIRECTIVES (AD) / SERVICE BULLETIN (SB) MONTHLY SUMMARY

 REFERENCE NO.
 CAMO/ADSB/AW139/2024-06

 DATE
 4/7/2024

AIRWORTHINESS DIRECTIVES (AD) / SERVICE BULLETIN (SB) ISSUANCE FOR MONTH OF JUNE 2024

THE PARTY OF		ABYTE SATISTIC		MANAGE M		CO TOWN TOWN		AIRCRAFT REGN. & COMPLIANCE									
Tax T							NO.1 FNGINE (PCF-KB07A2) NO.1 FNGINE				72-02(3131	5)	N	172-03(3131			
SB/AD NO		ISSUE/	SUBJECT	SB CLASSIFICATION/	COMPLIANCE TIME	TIC NO.					NO.1 ENGINE (PCE-KB0740)			.1 ENGINE (REMARKS		
SB/AD NO		REVISION DATE	SOBJECT	CATEGORIES	COMPLIANCE TIME		NO.2 ENGINE(PCE-KB0739)			NO.2 ENGINE(PCE-KB0732)			NO.2 ENGINE (NIL)			Remains	
							APPLICABILITY	STATUS	WORKPACK REF NO	APPLICABILITY	STATUS	WORKPACK REF NO	APPLICABILITY	STATUS	WORKPACK REF NO		
		The state of the s		And a second sec			AIRWORTHINES	DIRECTIVE (EI	IGINE)					1			
				NIL				2-01 WITHDRA VICE (CRASHED			NIL			NIL		NIL	
								-		L (SB NO			_) APPROVED AND		JIRED IN THE FUTURI	a. ·	
	PREPARED E (SIGN / STA	BY	FIRDAUS BIN	SHAHREEN		VERIFIED BY (SIGNIDED) STAMP):	uty Continuit Galay A CONTINUING (CAM)/	Airworthin	Ness Mana MANAGER B WING	CAL (DCALA)		ENDORSED BY (SIGN / STAMP):	DESIGN ACC		PRESENTATIVE	BIN HAJI OTHMAN	
DATE: 0 4/ 07/				2024		DATE:	04/0	1/2024				DATE: 05/07/Ban Agensi Pengu			tua Penolong Jahagian Keju nguatkuasaan	olong Pengarah Kejuruteraan Isaan Maritim Malaysia In Dalam Negeri	